



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJK 1007Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	DENTED / DEFORMED	1,250.00	845.10
1	FRONT BUMPER LOWER CENTRE GRILLE	DEFORMED / TWISTED	288.50	245.20
1	FRONT BUMPER FOG LAMP N/S	CRACKED	556.20	516.40
1	FRONT BUMPER FOG LAMP CHROME N/S	SCRATCHED	350.00	253.90
1	FRONT BUMPER SIDE RETAINER N/S	NOT NECESSARY	85.10	-
1	FRONT BUMPER SPONGE	SERVICEABLE	188.20	-
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	399.10	-
1	FRONT BUMPER CENTRE CHROME	CRACKED	1,020.00	818.40
1	FRONT GRILLE ASSY	CRACKED	1,960.00	1,800.00
1	AIR CON CONDENSER	PUNCTURE	1,999.10	1,276.00
1	AIR CON CONDENSER SIDE GARNISH N/S	DEFORMED / TORN	85.00	85.00
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	745.10	-
1	BONNET	NOT NECESSARY	855.90	-
1	BONNET OUTER CHROME	SCRATCHED	688.00	465.10
1	FRONT FENDER N/S	TO REPAIR SEE LABOUR	1,312.50	-
1	HEADLAMP ASSY N/S	CRACKED	6,250.00	4,280.00
	LESS 25% DISCOUNT		-4,508.18	-2,646.28
			13,524.52	7,938.82
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING.		50.00	20.00
	TO SPRAY RUST PROOFING.	NOT NECESSARY	50.00	-
	TO REFILL AIR CON GAS.	NOT NECESSARY	120.00	-
	TO RESET & REPROGRAMME SYSTEM.		180.00	80.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT, FRONT SUPPORT PANEL AND FRONT FENDER N/S.		680.00	480.00

Report Ref No. CS/TP21006369/Uqf3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY & SPRAY PAINTING.		900.00	550.00
			1,980.00	1,130.00
GRAND TOTAL			15,504.52	9,068.82
RECOMMENDED COST OF REPAIRS				9,068.82

Report Ref No. CS/TP21006369/Uqf3e2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.