

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0456/2021/KS
DATE : 26-May-21
WIP : 29077

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 2/5/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR J JEYASEELAN
ADDRESS : BLK 590A ANG MO KIO ST 51
#14-05
SINGAPORE 561590
TELEPHONE : HP +65 98524060
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070179492
VEHICLE NO : SMX 2259 C
MODEL CODE : AUDI A5 SPORTBACK 2.0
MODEL YEAR : 31/12/2020
ENGINE NO : DEM 028588
CHASSIS NO : WAUZZZF56MA018259
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-May-21
PLACE OF ACCIDENT : TRAFFIC JUNCTION OF HOUGANG ST 91

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SMX 2259 C

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	S/N \$ 480.00	✓✓
2	TO DISMANTLE AND RENEW FRONT BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,200.00 500	✓
3	TO RESPRAY FRONT BUMPER	\$ 1,000.00 550	✓
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓✓
TOTAL LABOUR CHARGES		: \$ 2,872.00	

Car-in 22/6/21 mp: 29077.

L2

PREMIUM AUTOMOBILES



55, UBI ROAD 1, SINGAPORE 408699
TEL: 6364 2323 FAX: 6841 1183
EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 2259 C

Alg - A Lem
- 3 days

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER 2 torn	1 S	2,342.00	✓ 1873.60
2	FRONT BUMPER GRILLE CENTER Not NN	1 S	196.00	+
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE 2 could	1 S	262.00	✓ 209.20
4	FRONT BUMPER AIR GUIDE GRILLE LH / RH 2 NN	2 S	270.00	+
5	FRONT BUMPER TRIM LH / RH	2 S	96.00	+
6	FRONT BUMPER TRIM - CENTER	1 S	114.00	+
7	FRONT BUMPER CLOSING ELEMENT 2 not	1 S	262.00	+
8	FOAM FILLER PIECE 2 could	1 S	146.00	✓ 116.40
9	FRONT BUMPER REINFORCEMENT BEAM 2 Dented	1 S	845.00	✓ 675.60
10	FRONT BUMPER TOP COVER 2 torn	1 S	127.00	✓ 101.60
11	"CAUTION" STICKER 2 NN	1 S	14.00	✓ 10.88
12	AIR COND STICKER 2 NN	1 S	8.00	✓ 5.68
13	FRONTAL LOCK CARRIER BRACKET 2 could	1 S	137.00	✓ 109.60
14	LOCK CARRIER SUPPORT LH / RH 2 NN	2 S	58.00	+
15	RADIATOR GRILLE 2 could	1 S	1,694.00	✓ 1355.20
16	FRONT CAMERA COVER 2 NN	1 S	166.00	✓ 132.80
17	FRONT CAMERA BRACKET 2 nn	1 S	17.00	×
18	FRONT CAMERA 2 NN	1 S	1,141.00	+
19	FRONT CAMERA ADAPTER 2 NN	1 S	198.00	+
20	FRONT PARKING AID SENSOR	2	TBC	+
SUB TOTAL SPARE PARTS			S 8,093.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT

Syp - Bonnet Impact Protection - center could
Add - 8W6 823 124

Adrian Lj
23/06/21
HLS

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO.SMX 2259 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT PARKING AID SENSOR SEAL RING <i>New</i>	1	\$ 14.00	X
22	RADIATOR AIR GUIDE LH / RH <i>New</i>	2	\$ 64.00	X
23	RADIATOR AIR GUIDE LH / RH <i>New</i>	2	\$ 32.00	X
24	RADIATOR AIR GUIDE UPPER / LOWER <i>New</i>	2	\$ 32.00	X
25	FRONT NO PLATE <i>Dented</i>	S/N	\$ 60.00	60
26	SUNDRIES		\$ 250.00	✓ 2.56
TOTAL SPARE PARTS		:	\$ 8,545.00	
TOTAL LABOUR CHARGES		:	\$ 2,872.00	
GRAND TOTAL		:	\$ 11,417.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian King.
SURVEYED DATE : 02/06/21.
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 03 Days.

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT