

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 06 Jan 2022

Preliminary Advice

Insured : SLP5671D
Vehicle No
TP Vehicle No : SH6716L
Make : HYUNDAI AE IONIQ HEV DCT
Date of Inspection : 03/06/2021
Inspection At : BIFROST AUTO PTE LTD (SIN MING) (HQ)
BLK 9 SECTOR C, #01-42 SIN MING INDUSTRIAL ESTATE
SINGAPORE 575644

Accident Date : 01/06/2021
Assignment Date : 03/06/2021
Est. Duration of Repair : 12

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 51,903.36
Revised Amount	:S\$ 32,879.10
Check Items (Estimated)	:S\$ 0.00
Total	:S\$ 32,879.10

Lump Sum Repair	:S\$ 26,000.00
-----------------	----------------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$

COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
 - () The vehicle is not economical for repair
 - () Part-by-Part repair
 - (X) Lump Sum repair
-
- (X) The above survey was conducted on a 'without prejudice' basis.
Please note that the preliminary advice amount (Revised & Check Items)
stated are subject to consistency check, part prices and labour cost.