

6/7/2021

Repairer Estimates



PROGRESSIVE
CAR CARE PTE LTD

Progressive Car Care Pte Ltd
(Co. Reg. No. 201006949C)
Blk 3022A Ubi Road 1 #01-45/ 46 S408716
T: +65 6741 5336 | F: +65 6741 7208
E: claims@procarcare.com.sg
W: www.procarcare.com.sg

INSURER: **AIG Asia Pacific Insurance Pte. Ltd. (SG)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD 0521-7913
Policy No:	2070150600	Date of Loss:	25/05/2021
Vehicle Reg. No.:	YP4939K	Driveable?	NO
Driver Age/Info:	64 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	NO
Insured/Claimant:	ALANTAC INDUSTRIAL SERVICES PTE LTD	Contact No:	+656598235671
Driver:	MOHD KHALID BIN ABD JALAL		
Make/Model:	mitsubishi canter, 3.0 D (M)	Vehicle Reg. Date:	29/11/2016
Vehicle Colour:	WHITE	Chassis No:	FEB21EA20782
Engine No:	4P10C27076		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Description of Accident/Loss	REFER TO ATTACHE		
Remarks:	VEHICLE IS IN WORKSHOP		
Present Location:	PROGRESSIVE CAR CARE PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	4,455.00
Miscellaneous Items	11.00
Labour	292.80
Paintwork Labour	165.56
Towing	0.00
Gross Total (\$\$)	4,924.36
+ GST 7.00% (\$\$)	344.71
Nett Amount (\$\$)	5,269.07

This claim is handled by: LILY LIM

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 03 Jun 2021)**Parts:** N/A MITSUBISHI CANTER 3.0 D (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Progressive Car Care Pte Ltd/YP4939K/03/06/2021 14:15**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*FILTER TUBE	0.00	0.00	*420.00 F
2	1	NA	*FRT TANK STRAP	0.00	0.00	*300.00 F
3	1	NA	*FUEL PUMP HARNESS	0.00	0.00	*280.00 F
4	1	NA	*FUEL TANK	0.00	0.00	*1,900.00 F
5	1	NA	*FUEL TUBE 1	0.00	0.00	*450.00 F
6	1	NA	*FUEL TUBE 2	0.00	0.00	*400.00 F
7	1	NA	*REAR TANK STRAP	0.00	0.00	*300.00 F
Sub Total (S\$)						4,050.00
+ Margin on L,N Items 10.00% (S\$)						405.00
Total Parts (S\$)						4,455.00

Progressive Car Care Pte Ltd/YP4939K/03/06/2021 14:15. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

6/7/2021

Repairer Estimates

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (\$\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	Total Paint Labour	New	124.80
2	Total Paint Materials	New	40.76
<u>Labour Items</u>			
3	Total Panel/Mechanical Labour	New	250 202.80
Gross Labour Cost (\$\$)			458.36

Progressive Car Care Pte Ltd/YP4939K/03/06/2021 14:15. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-O-LINER MARK 5 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs.

NA2 LKK

7/6/2021 1230

L/S

4 DAYS

AFTER REPAIR PHOTOS

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: