

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: India International Insurance Pte Ltd
64 Cecil Street
#04-00 IOB Building
Singapore 049711

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Priya

Date: 07 Jun 2021

Preliminary Advice

Vehicle No	: SMM6425X	Accident Date	: 02/06/2021
Make	: HYUNDAI KONA	Policy No.	: D21MFL0000447
Assignment Date	: 03/06/2021	Excess	: S\$0.00
Date of Inspection	: 04/06/2021	Est. Duration of Repair	: 10
Inspection At	: PEGASUS ENGINEERING & TRADING PTE LTD (KIAN TECK) 74 KIAN TECK ROAD SINGAPORE 628800		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	38,404.48
Revised Amount	:S\$	11,152.56
Check Items (Estimated)	:S\$	22,831.45
Total	:S\$	33,984.01

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	113,000.00
COE / PARF Rebate	:S\$	50,662.00
Salvage Value	:S\$	
Margin for Repair	:S\$	62,338.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :