

SJE :

Date of Survey : _____

Date of ReSurvey: _____

Contacts : _____

Vehicle Nos : **SLU 2204 M**

Model : **Mazda 2**

Year : _____

Chassis No : _____

After-Paint: _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Tailgate	1	\$ 1,358.00	\$ 1,358.00	DD✓
2	Tailgate logo	1	\$ 88.20	\$ 88.20	NEC✓
3	Tailgate emblem 'Mazda 2'	1	\$ 68.90	\$ 68.90	NDX
4	Tailgate inner lock	1	\$ 219.80	\$ 219.80	NDX
5	Tailgate inner lock striker	1	\$ 68.10	\$ 68.10	NDX
6	Tailgate inner trim board	1	\$ 355.90	\$ 355.90	NSX
7	Tailgate weatherstrip	1	\$ 189.60	\$ 189.60	NECV
8	Tailgate antenna sensor	1	\$ 358.60	\$ 358.60	BRV
9	Tailgate windscreen moulding	1	\$ 157.50	\$ 157.50	NECV
10	Rear bumper	1	\$ 1,096.70	\$ 1,096.70	BRV
11	Rear bumper side retainer	2	\$ 37.60	\$ 75.20	NECV
12	Rear bumper reinforcement	1	\$ 684.20	\$ 684.20	DDXR
13	Rear bumper number plate lamp	2	\$ 84.00	\$ 168.00	NDX
14	Rear end panel	1	\$ 830.40	\$ 830.40	DDXR
15	Rear end panel top garnish	1	\$ 109.40	\$ 109.40	BRV
16	Taillamp	2	\$ 465.40	\$ 930.80	BRV
17	Taillamp lower bracket	2	\$ 62.80	\$ 125.60	NSX
			Parts Sub Total :	\$ 7,307.90	
			Discount :	\$ 1,461.58	
			PARTS TOTAL :	\$ 5,846.32	

@ 20%
2992.30
598.46
2393.84

20%

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	Sundries	1	\$ 80.00	\$ 80.00	NNX
2	Tailgate sealant	1	\$ 100.00	\$ 100.00	NNX
3	Tailgate inner trim board clips	1	\$ 50.00	\$ 50.00	NECV
4	Tailgate windscreen sealant	1	\$ 100.00	\$ 100.00	NECV
5	Tailgate windscreen inner seal	1	\$ 60.00	\$ 60.00	NSX
6	Tailgate windscreen prime & cleaner	1	\$ 80.00	\$ 80.00	NNX
7	Rear bumper clips	1	\$ 50.00	\$ 50.00	NECV
8	Rear bumper reverse sensor	2	\$ 250.00	\$ 500.00	SC✓
9	Rear end panel sealant	1	\$ 100.00	\$ 100.00	NECV
10	Rear end panel top garnish clips	1	\$ 50.00	\$ 50.00	NECV
11	Taillamp seal	2	\$ 60.00	\$ 120.00	NECV
12	Taillamp clips	2	\$ 50.00	\$ 100.00	NSX
13	Rear number plate w/casing	1	\$ 80.00	\$ 80.00	BT✓
			SPECIAL NETT TOTAL :	\$ 1,470.00	

540.00

Nos.	LABOUR	S\$
1	R&R tailgate component	\$ 80.00 150.00 ✓
2	R&R tailgate windscreen	\$ 120.00 250.00 ✓
3	R&R rear bumper reverse sensor	\$ 60.00 100.00 ✓
4	Upholstery	\$ 200.00 NN
5	Check wiring	\$ 30.00 100.00 ✓
6	Panel beating	\$ 800.00 1,200.00 ✓
7	Rust proofing	\$ 200.00 NN
8	spray painting	\$ 600.00 1,200.00 ✓
LABOUR TOTAL :		\$ 3,400.00

Survey Resurvey
 3/6/2021 3/6/2021
 TCU in TCU in
 lin lin
 1300hrs 1600hrs

Lump sum repair
 Repair days 5

1610.00
 PARTS TOTAL : \$ 5,846.32
 SPECIAL NETT TOTAL : \$ 1,470.00
 LABOUR TOTAL : \$ 3,400.00
 GRAND TOTAL : \$ 10,716.32

Parts 2,393.84
 SN 540.00
 Labour 1,610.00
 4543.84
 @ 20% 908.77
 3635.07

45 3650/r

TCU in lin
 14/6/2021

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: