

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 16 Jul 2021

Preliminary Advice

Insured : GBH2905K
Vehicle No
TP Vehicle : SMX2985P Accident Date : 03/06/2021
No
Make : MERCEDES-BENZ GLA180 Assignment Date : 06/06/2021
Date of : 04/06/2021 Est. Duration of : 6
Inspection Repair
Inspection At : JWG INTERNATIONAL PTE LTD (HQ)
BLK 10, ANG MO KIO IND PARK 2A,, #03-08 AMK
AUTOPOINT
SINGAPORE 568047

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	49,634.67
Revised Amount	:S\$	12,325.55
Check Items (Estimated)	:S\$	0.00
Total	:S\$	12,325.55

Lump Sum Repair	:S\$	9,850.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$

COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :