

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 23 Jun 2021

Preliminary Advice

Insured Vehicle No	: GBH2673D	Accident Date	: 02/06/2021
TP Vehicle No	: GBC8595H	Assignment Date	: 03/06/2021
Make	: TOYOTA HIACE	Est. Duration of Repair	: 10
Date of Inspection	: 03/06/2021		
Inspection At	: LIU'S BROTHER AUTO ENGINEERING WORKSHOP (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,271.90
Revised Amount	:S\$	8,508.33
Check Items (Estimated)	:S\$	0.00
Total	:S\$	8,508.33
 Lump Sum Repair	 :S\$	 6,800.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :