

Survey
3/6/2021
T. G. Lim Mui
1520 hrs

Resurvey
3/6/2021
T. G. Lim Mui
1820 hrs

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Vehicle No:
Model and make:
Chassis number:

SMW 1145J
SMW1145U
BMW335i

Qty Spare parts

List price

1	Bootlid	\$	✓ 1,382.00	BR ✓
1	Bootlid lock	\$	✓ 193.00	JH ✓
1	Bootlid lock catch	\$	54.00	NDX
1	Bootlid RH lamp assy	\$	327.75	373.00 } BR ✓
1	Bootlid LH lamp assy	\$	327.75	373.00 }
1	Bootlid RH hinge	\$	173.00	173.00 } NDX
1	Bootlid LH hinge	\$	173.00	173.00 }
1	Bootlid inner trim	\$	281.00	281.00 } NDX
1	Bootlid weatherstrip	\$	258.00	258.00 }
1	Bootlid RH number plate lamp	\$	57.00	57.00 } NDX
1	Bootlid LH number plate lamp	\$	57.00	57.00 }
1	Rear bumper	\$	✓ 1,472.00	BR ✓
1	Rear bumper RH side bracket	\$	✓ 114.00	✓
1	Rear bumper LH side bracket	\$	✓ 114.00	NECV ✓
1	Rear bumper centre bracket	\$	✓ 152.00	BR ✓
1	Rear bumper lower garnish	\$	220.00	368.00 BR ✓
1	Rear bumper reinforcement	\$	395.00	595.00 DD ✓
1	Rear bumper tow cover	\$	✓ 42.00	DD ✓
1	Rear bumper RH side under cover	\$	✓ 78.00	BR ✓
1	Rear bumper LH side under cover	\$	✓ 78.00	BR ✓
1	Rear bumper RH side reverse sensor	\$	232.00	288.00 }
1	Rear bumper RH reverse sensor	\$	232.00	288.00 } SCV ✓
1	Rear bumper LH reverse sensor	\$	232.00	288.00 }
1	Rear bumper LH side reverse sensor	\$	232.00	288.00 }
4	Rear bumper reverse sensor O-rings	\$	✓ 18.00	NECV ✓
4	Rear bumper reverse sensor brackets	\$	148.00	NSX
1	Rear bumper reverse sensor wire harness	\$	212.00	NNX
1	End panel	\$	✓ 771.00	DD ✓
1	End panel inner garnish	\$	120.00	159.00 BR ✓
1	Spare tyre panel	\$	985.00	985.00 }
1	Spare tyre panel top board	\$	252.00	252.00 }
1	Spare tyre panel compartment	\$	219.00	219.00 } NDX
1	Spare tyre panel RH side tool tray	\$	189.00	189.00 }
1	Spare tyre panel LH side tool tray	\$	189.00	189.00 }
1	Rear windscreen glass with rubber moulding	\$	1,178.00	NDX
1	Rear RH fender	\$	✓ 1,650.00	DD ✓
1	Rear RH fender inner trim board	\$	742.00	742.00 }
1	Rear RH fender splash shield	\$	376.00	376.00 } NDX
1	Rear RH fender glass with rubber moulding	\$	603.00	603.00 }
1	Rear LH fender	\$	✓ 1,650.00	DD ✓

2011

1	Rear LH fender inner trim board		\$	742.00	NDX
1	Rear LH fender splash shield		\$	376.00	NDX
1	Rear LH fender glass with rubber moulding		\$	337.00	603.00 NECV ✓
1	RH taillamp assy		\$	✓	553.00 BR ✓
1	RH taillamp lower bracket		\$		412.00 NDX
1	RH taillamp panel		\$	✓	136.00 DD ✓
1	LH taillamp assy		\$		553.00 BR ✓
1	LH taillamp lower bracket		\$		413.00 NDX
1	LH taillamp panel		\$		136.00 NDX
1	Exhaust silencer assy (Twin pipes)	To provide invoice to amende *	\$	10,000.00	1,068.00 BT ✓ *
2	Exhaust silencer heat shields	@ 153.90	\$	307.80	390.00 DD ✓
2	Exhaust silencer rubber mountings	@ 37.00	\$	74.00	120.00 } NEC ✓
2	Exhaust silencer gaskets		\$	✓	74.00
6	Exhaust silencer clamps	@ 66.00	\$	396.00	511.80
				21,910.30	
				\$	34,466.80
				-5%	\$ 1,723.34
				\$	32,743.46

Qty Spare parts

Special Nett price

1	Bootlid spoiler		\$	850.00	NSX
1	Bootlid carbon fibre centre emblem		\$	✓ 89.55	120.00
1	Bootlid "M" emblem		\$	✓ 89.55	120.00
1	Bootlid black vinyl wrap sticker	To provide invoice *	\$	*	350.00 NNX
1 set	Bootlid inner trim clips		\$	30.00	100.00 NECV
1	Rear number plate (chrome wordings)		\$	50.00	120.00 NECV
1	Rear windscreen glass sealant		\$	40.00	100.00 NECV
1	Rear windscreen glass inner seal		\$	40.00	80.00 NECV
1 set	Rear bumper clips		\$	30.00	100.00 NECV
1	Rear bumper lower carbon fibre spoiler		\$	850.00	✓ 1,100.00 MIS ✓
1	Rear RH fender joint sealant		\$		100.00 NNX
1	Rear RH fender black vinyl wrap sticker	To provide invoice *	\$	*	750.00
1	Rear RH fender wordings sticker		\$		480.00 } NNX
1	Rear RH fender glass sealant		\$		100.00
1	Rear RH fender glass inner seal		\$		100.00 } NNX
1	Rear LH fender joint sealant		\$		100.00
1	Rear LH fender black vinyl wrap sticker	To provide invoice *	\$	*	750.00
1	Rear LH fender wording sticker		\$		480.00 } NNX
1	Rear LH fender glass sealant		\$		100.00
1	Rear LH fender glass inner seal		\$		100.00 } NNX
4	Exhaust silencer carbon fibre finishers	@ 250.00	\$	✓ 1,000.00	1,152.00 DD ✓
1	End panel joint sealant		\$	40.00	100.00 NECV ✓
1	Spare tyre panel joint sealant		\$		100.00 NNX
				500.00	2,000.00 NEC ✓

Labour and painting

Labour charges to remove, check, replace and reinstall damages bodyparts.
To panel beating, cut / weld and re-align all affected panels

2,759.10
\$ 1,400.00 2,800.00 ✓

* To provide invoice before adding to total COR *

* COR to be amended once invoices are provided. *

INVOICE

Spray painting on affected panels	\$ 800.00	2,000.00 ✓
Check wiring and lighting system	\$ 60.00	180.00 ✓
Apply rust coating on affected areas	\$	150.00 N/A ✓
Remove and reinstall rear RH fender glass to assist repair	\$ 70.00	180.00 ✓
Remove and reinstall rear LH fender glass to assist repair	\$ 70.00	150.00 ✓
Remove and replace rear inner trims, garnish, roof lining, seats and boards to assist repairs	\$ 120.00	380.00 ✓
Remove and replace rear bumper reverse sensor and wire harness	\$ 60.00	180.00 ✓
Remove and replace exhaust silencer, rubber mountings and heat shield to assist repairs	\$ 100.00	220.00 ✓
Reset and diagnose electronic control unit	\$ 120.00	320.00 ✓

Total: \$ 46,725.46

Lum Sum repair

Repair days 12

2800.00

Part 20,814.79
S/N 2,759.10
Labour 2880.00
26,373.89
@20% 5,274.79
21,099.11

HS 21,100/22

To amend car invoices must be provided.

TCrim Lin
18/6/2021

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: