



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

QBE INSURANCE (SINGAPORE) PTE LTD

INV No. AC2105812

1 RAFFLES QUAY #29-10 SOUTH TOWER  
SINGAPORE 048583

INV Date 18/08/2021

Reference CC3/QBE21006395/R1ea3q

Code QBE

### PROFESSIONAL SERVICE FEE

Vehicle No. SHF 365X

Insured Veh. XD 8528L

Claim No. VC014576

Policy No. 8-V0025362-MVA-R001

Accident Date 01/06/2021

Inspection Date 02/06/2021

| Description                    | Total         |
|--------------------------------|---------------|
| Third Party Express Settlement | 400.00        |
| <b>Subtotal</b>                | <b>400.00</b> |
| <b>GST (7%)</b>                | <b>28.00</b>  |
| <b>Grand Total</b>             | <b>428.00</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                      |                 |                                                               |  |
|----------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|-----------------|---------------------------------------------------------------|--|
| QBE INSURANCE (SINGAPORE) PTE LTD<br>1 RAFFLES QUAY #29-10 SOUTH<br>TOWERSINGAPORE 048583                                              |                                                                                      |                 | Ref: CC3/QBE21006395/R1ea3q2<br>Date: 18/08/2021<br>Code: QBE |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                      |                 |                                                               |  |
| Insured Veh.                                                                                                                           | XD 8528L                                                                             | Veh. Inspected  | SHF 365X                                                      |  |
| Policy No.                                                                                                                             | 8-V0025362-MVA-R001                                                                  | Coverage (\$)   | 0.00                                                          |  |
| Claim No.                                                                                                                              | VC014576                                                                             | Excess (\$)     | 0.00                                                          |  |
| Assign From                                                                                                                            | JENNY                                                                                | Assign Date     | 02/06/2021                                                    |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                      |                 |                                                               |  |
| Make & Model                                                                                                                           | TOYOTA PRIUS HYBRID 1.8<br>CVT                                                       | c.c             | 1798                                                          |  |
| Engine No.                                                                                                                             | HIDDEN                                                                               | Year of Reg.    | 2017                                                          |  |
| Chassis No.                                                                                                                            | JTDKB3FU803578442                                                                    | Colour          | MAROON                                                        |  |
| Odometer                                                                                                                               | 432821 KM                                                                            | Steering        | IN ORDER                                                      |  |
| Brakes                                                                                                                                 | IN ORDER                                                                             | Modification    | SPORTS RIM                                                    |  |
| General                                                                                                                                | FAIR                                                                                 |                 |                                                               |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                      |                 |                                                               |  |
|                                                                                                                                        | Size                                                                                 | Make            | Balance                                                       |  |
| R/H Front Tyre                                                                                                                         | 195/65 R15                                                                           | YOKOHAMA        | 6 mm                                                          |  |
| L/H Front Tyre                                                                                                                         | 195/65 R15                                                                           | YOKOHAMA        | 6 mm                                                          |  |
| R/H Rear Tyre                                                                                                                          | 195/65 R15                                                                           | YOKOHAMA        | 6 mm                                                          |  |
| L/H Rear Tyre                                                                                                                          | 195/65 R15                                                                           | YOKOHAMA        | 6 mm                                                          |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                      |                 |                                                               |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.                                                             |                                                                                      |                 |                                                               |  |
| <b>5. General Information</b>                                                                                                          |                                                                                      |                 |                                                               |  |
| Accident Date                                                                                                                          | 01/06/2021                                                                           | Inspection Date | 02/06/2021                                                    |  |
| Survey held at                                                                                                                         | SMRT AUTOMOTIVE SERVICES PTE LTD<br>60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705 |                 |                                                               |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                      |                 |                                                               |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                      |                 |                                                               |  |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                                      |                 |                                                               |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                      |                 | 8 Working Days                                                |  |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 365X

| Qty | Description of Parts                                                           | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--------------------------------------------------------------------------------|-----------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>                                             |           |                           |                   |
| 1   | EMBLEM SUB-ASSY REAR (DISC 25%)                                                | NECESSARY | 46.30                     | 34.73             |
| 1   | TAIL GATE LOWER GLASS SUB-ASSY ,BACK DOOR (DISC 25%)                           | BROKEN    | 725.90                    | 544.43            |
| 1   | NAME PLATE (PRIUS) LUGGAGE COMPARTMENT (DISC 25%)                              | NECESSARY | 52.30                     | 39.23             |
| 1   | NAME PLATE (HYBRID) ,LUGGAGE COMPARTMENT (DISC 25%)                            | NECESSARY | 52.30                     | 39.23             |
| 1   | MOULDING SUB-ASSY ,ROOF DRIP SIDE FINISH (DISC 25%)                            | NECESSARY | 52.70                     | 39.53             |
| 1   | MOULDING SUB-ASSY ,ROOF TOP (DISC 25%)                                         | NECESSARY | 637.40                    | 478.05            |
| 1   | TAIL GATE BACK DOOR OUTSIDE GARNISH SUB (DISC 25%)                             | DEFORMED  | 891.20                    | 668.40            |
| 1   | REAR BUMPER REINFORCEMENT (DISC 25%)                                           | BENT      | 318.80                    | 239.10            |
| 1   | COVER ,RR BUMPER ASSY (DISC 25%)                                               | DEFORMED  | 423.90                    | 317.93            |
| 1   | GUARD ,RR BUMPER ,LOWER (DISC 25%)                                             | DEFORMED  | 558.30                    | 418.73            |
| 10  | CLIPS PIECE ,FRT & RR BUMPER @\$1.50 (DISC 25%)                                | NECESSARY | 15.00                     | 11.25             |
| 2   | SEAL ,RR BUMPER ARM ,RH & LH @\$11.00 (DISC 25%)                               | NECESSARY | 22.00                     | 16.50             |
| 3   | PAD ,RR BUMPER CTR @\$2.20 (DISC 25%)                                          | NECESSARY | 6.60                      | 4.95              |
| 2   | PAD ,RR BUMPER ,RH & LH ,3 @\$3.80 (DISC 25%)                                  | NECESSARY | 7.60                      | 5.70              |
| 2   | PAD ,RR BUMPER ,RH & LH ,2 @\$3.80 (DISC 25%)                                  | NECESSARY | 7.60                      | 5.70              |
| 2   | PAD ,RR BUMPER ,RH & LH ,1 @\$3.80 (DISC 25%)                                  | NECESSARY | 7.60                      | 5.70              |
| 1   | END PANEL ,COVER ,DECK TRIM REAR PAD ,RR BUMPER ,RH & LH ,3 @\$3.80 (DISC 25%) | DEFORMED  | 122.80                    | 92.10             |
| 1   | PANEL ASSY ,DECK TRIM SIDE ,RH (DISC 25%)                                      | DEFORMED  | 344.70                    | 258.53            |
| 1   | PANEL ASSY ,DECK TRIM SIDE ,LH (DISC 25%)                                      | DEFORMED  | 344.70                    | 258.53            |
| 2   | TAIL GATE BACK DOOR HINGE ASSY ,RH & LH @\$59.10 (DISC 25%)                    | CRACKED   | 118.20                    | 88.65             |
| 1   | BOX ,DECK FLOOR ,LH (DISC 25%)                                                 | CRACKED   | 303.40                    | 227.55            |
| 1   | END PANEL SUB-ASSY ,BODY LOWER BACK (DISC 25%)                                 | BENT      | 629.80                    | 472.35            |
| 1   | TAIL GATE DAM ,BACK DOOR GLASS UPPER (DISC 25%)                                | BENT      | 27.90                     | 20.93             |
| 1   | TAIL GATE PANEL SUB-ASSY ,BACK DOOR (DISC 25%)                                 | BENT      | 929.60                    | 697.20            |
| 1   | LAMP SET ,STOP CENTER (DISC 10%)                                               | CRACKED   | 186.50                    | 167.85            |
| 1   | SOLAR FILM (SN)                                                                | NECESSARY | 125.00                    | 125.00            |

Report Ref No. CC3/QBE21006395/R1ea3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

| Qty | Description of Parts                    | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-----------------------------------------|---------------|---------------------------|-------------------|
| 1   | STICKER DECAL 6555 8888 (SN)            | NECESSARY     | 21.60                     | 21.60             |
| 1   | SMRT LOGO (SN)                          | NECESSARY     | 7.80                      | 7.80              |
| 3   | SEALANT W/SCREEN @\$37.00 (SN)          | NECESSARY     | 111.00                    | 111.00            |
| 2   | PIXEL STICKER @\$60.00 (SN)             | NECESSARY     | 120.00                    | 120.00            |
| 2   | SEALANT W/SCREEN @\$37.00 (SN)          | NECESSARY     | 74.00                     | 74.00             |
| 1   | SOLAR FILM                              | NOT NECESSARY | 350.00                    | -                 |
| 1   | SENSOR REVERSE                          | SERVICEABLE   | 180.00                    | -                 |
| 1   | ANTENNA ELECTRICAL KEY                  | SERVICEABLE   | 60.30                     | -                 |
| 1   | LENS & BODY ,REAR COMBINATION LAMP ,RH  | SERVICEABLE   | 438.10                    | -                 |
| 1   | LENS & BODY ,REAR COMBINATION LAMP ,LH  | SERVICEABLE   | 438.10                    | -                 |
| 1   | LENS & BODY ASSY ,RR BUMPER ,RH         | SERVICEABLE   | 486.80                    | -                 |
| 1   | LENS & BODY ASSY ,RR BUMPER ,LH         | SERVICEABLE   | 486.80                    | -                 |
| 1   | COVER ,REAR COMBINATION LAMP ,RH        | SERVICEABLE   | 54.00                     | -                 |
| 1   | COVER ,REAR COMBINATION LAMP ,LH        | SERVICEABLE   | 54.00                     | -                 |
| 1   | COVER ,REAR FLOOR UNDER ,RH             | SERVICEABLE   | 169.50                    | -                 |
| 2   | TAIL GATE BACK DOOR HINGE ASSY ,RH & LH | SERVICEABLE   | 59.10                     | -                 |
| 1   | END PANEL COVER ,DECK TRIM REAR         | SERVICEABLE   | 122.80                    | -                 |
| 1   | END PANEL COVER ,DECK TRIM SERVICE HOLE | SERVICEABLE   | 47.00                     | -                 |
| 1   | SPARE TYRE PANEL ,PAN ,REAR FLOOR       | SERVICEABLE   | 564.80                    | -                 |
| 1   | WIRE ,TAIL GATE BACK DOOR NO.2          | SERVICEABLE   | 246.80                    | -                 |
| 1   | WIRE ,TAIL GATE BACK DOOR               | SERVICEABLE   | 246.80                    | -                 |
| 1   | LAMP SET ,STOP CENTER                   | SERVICEABLE   | 186.50                    | -                 |
| 1   | TAIL GATE STRIKER ASSY ,BACK DOOR       | SERVICEABLE   | 24.90                     | -                 |
| 1   | TAIL GATE LOCK COVER ,BACK DOOR         | SERVICEABLE   | 25.30                     | -                 |
| 1   | TAIL GATE LOCK ASSY ,BACK DOOR          | SERVICEABLE   | 452.10                    | -                 |
| 1   | TAIL GATE STAY ASSY ,BACK DOOR ,LH      | SERVICEABLE   | 235.00                    | -                 |
| 1   | TAIL GATE STAY ASSY ,BACK DOOR ,RH      | SERVICEABLE   | 235.00                    | -                 |
| 1   | TAILGATE TRIM LOWER                     | SERVICEABLE   | 218.50                    | -                 |
| 1   | TAILGATE TRIM LH                        | SERVICEABLE   | 92.10                     | -                 |
| 1   | TAILGATE TRIM ,UPPER                    | SERVICEABLE   | 50.50                     | -                 |
| 1   | TAIL GATE GLASS SUB-ASSY ,BACK DOOR     | SERVICEABLE   | 1,569.70                  | -                 |
| 1   | BOX ,DECK FLOOR ,RH                     | SERVICEABLE   | 304.00                    | -                 |
| 1   | BOX ,DECK FLOOR ,LH                     | SERVICEABLE   | 303.40                    | -                 |

Report Ref No. CC3/QBE21006395/R1ea3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

| Qty                                                                                                                   | Description of Parts                                | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------|----------------------|---------------------------|-------------------|
| 1                                                                                                                     | BOARD ,REAR FLOOR NO.1                              | SERVICEABLE          | 502.20                    | -                 |
| 1                                                                                                                     | SEALANT SIKAFLEX                                    | SERVICEABLE          | 37.00                     | -                 |
| 1                                                                                                                     | END PANEL SUB-ASSY ,BODY LOWER BACK                 | SERVICEABLE          | 629.80                    | -                 |
| 1                                                                                                                     | WIRE ,TAIL GATE BACK DOOR NO.2                      | SERVICEABLE          | 246.80                    | -                 |
| 1                                                                                                                     | WIRE ,TAIL GATE BACK DOOR                           | SERVICEABLE          | 246.80                    | -                 |
| 1                                                                                                                     | TAILGATE BOARD ,COVER                               | SERVICEABLE          | 24.10                     | -                 |
| 1                                                                                                                     | TAILGATE BOARD ASSY                                 | SERVICEABLE          | 251.50                    | -                 |
| 1                                                                                                                     | TAILGATE TRIM RH                                    | SERVICEABLE          | 92.10                     | -                 |
| 1                                                                                                                     | TAIL GATE DAM ,BACK DOOR GLASS UPPER                | SERVICEABLE          | 27.90                     | -                 |
| 1                                                                                                                     | TAIL GATE WEATHERSTRIP ,BACK DOOR                   | SERVICEABLE          | 360.70                    | -                 |
| 1                                                                                                                     | COVER ,REAR FLOOR UNDER CENTER                      | SERVICEABLE          | 222.60                    | -                 |
| 1                                                                                                                     | FILLER ,RR BUMPER ,LH                               | SERVICEABLE          | 119.90                    | -                 |
| 1                                                                                                                     | FILLER ,RR BUMPER ,RH                               | SERVICEABLE          | 119.90                    | -                 |
| 1                                                                                                                     | COVER ,GUARD RR BUMPER LOWER                        | SERVICEABLE          | 14.80                     | -                 |
| 1                                                                                                                     | SPOILER SUB-ASSY ,REAR                              | TO REPAIR SEE LABOUR | 1,322.10                  | -                 |
| 1                                                                                                                     | TAIL GATE PANEL SUB-ASSY, BACK DOOR                 | TO REPAIR SEE LABOUR | 929.60                    | -                 |
| 1                                                                                                                     | MOULDING SUB-ASSY ,ROOF DRIP SIDE FINISH (DISC 25%) | NECESSARY            | 52.70                     | 39.53             |
|                                                                                                                       |                                                     |                      | 20,194.90                 | 5,651.78          |
| <b>LABOUR</b>                                                                                                         |                                                     |                      |                           |                   |
| PANEL BEATING & BODY WORK.INCLUSIVE OF THE REPAIR OF SPOILER SUB-ASSY ,REAR AND TAIL GATE PANEL SUB-ASSY, BACK DOOR . |                                                     |                      | 1,245.00                  | 800.00            |
| SPRAY PAINT.                                                                                                          |                                                     |                      | 2,036.00                  | 900.00            |
| TO TRANSFER REAR TAILGATE MECHANISM .                                                                                 |                                                     |                      | 180.00                    | 80.00             |
| TO REMOVE AND REFIX REAR WINDSCREEN .                                                                                 |                                                     |                      | 180.00                    | 120.00            |
| TO TRANSFER REAR TAILGATE MECHANISM .                                                                                 |                                                     | NOT NECESSARY        | 120.00                    | -                 |
| TO REMOVE AND REFIX TAILGATE GLASS .                                                                                  |                                                     |                      | 120.00                    | 60.00             |
| TO REMOVE AND REFIX REAR WINDSCREEN .                                                                                 |                                                     | NOT NECESSARY        | 120.00                    | -                 |
| TO TEST AND REFIX REVERSE SENSOR SYSTEM.                                                                              |                                                     |                      | 120.00                    | 60.00             |
| TO REMOVE AND REFIT WIRE HARDESS.                                                                                     |                                                     | NOT NECESSARY        | 120.00                    | -                 |
| TO REPLACE SUNDRY PARTS.                                                                                              |                                                     | NOT NECESSARY        | 100.00                    | -                 |
| TO CHECK WIRING AND SYSTEM FUNCTION .                                                                                 |                                                     | NOT NECESSARY        | 80.00                     | -                 |

Report Ref No. CC3/QBE21006395/R1ea3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

| Qty                                                                     | Description of Parts | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-------------------------------------------------------------------------|----------------------|---------------|---------------------------|-------------------|
|                                                                         | TO WASH AND VACUUM . | NOT NECESSARY | 60.00                     | -                 |
|                                                                         |                      |               | 4,481.00                  | 2,020.00          |
| GRAND TOTAL                                                             |                      |               | 24,675.90                 | 7,671.78          |
| RECOMMENDED COST OF LUMP SUM REPAIRS<br>(TO ITS PRE-ACCIDENT CONDITION) |                      |               |                           | 6,550.00          |

Report Ref No. CC3/QBE21006395/R1ea3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SHF 365X

### INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHF 365X

RE-INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

