





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 30/07/2021

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SG3028P
Case Reference Number	BUS/05/21/1036
Registration Date	1/2/2019
Company Type	SMRT Buses Ltd
Make	B5LH
Model	VOLVO - B5LH AUTO
Name of Driver	David Rajendran S/O Ramasamy
Type of Accident	Side Swipe
Accident Date and Time	30/5/2021 12:05 PM
Accident Reported Date and Time	2/6/2021 8:53 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24111154
Special Instruction to ARC,if any	SG3028P-RIGHT REAR PORTION GBK8041Y (TP) INSURED WITH
Prepared Date and Time	2/6/2021 10:42 AM
Chassis Number	YV3T1U22XJA192413
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,325.00	\$1,060.00
Total Spray Cost	\$864.00	\$694.00
Total Spare Part Cost	\$2,800.91	\$2,800.91
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$4,989.91	\$4,554.91
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	Boon Chew Tay	Rasul
ARC / Surveyor Sign Off Date	02/06/2021 10:54 AM	03/06/2021 3:04 PM
Signature		
Remarks		Before paint photo

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 30/07/2021

User ID : CatherineLee

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope		Quotation from AR				Adjusted by Surveyor, if applicable			
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.		\$1,325.00				\$1,060.00			
Total Labour		\$1,325.00				\$1,060.00			
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS		\$864.00				\$694.00			
Total Spray Painting & Panel Beating		\$864.00				\$694.00			
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		SEL74K43186100	Lower Rear Signal Led (UK-K431861)	1.00	\$465.80	10.00	\$419.22	Replace	Replace
		SEL74K43190100	Reverse Light 122mm LED (UK-K431901)	1.00	\$1,007.50	10.00	\$906.75	Replace	Replace
		M8C51042000000	GRP - RHS LAMP	1.00	\$894.50	10.00	\$805.05	Replace	Replace
		M8C75023100000	GRP - RHS REAR BUMPER GRP	1.00	\$572.10	10.00	\$514.89	Replace	Replace
			STICKER SMRT	1.00	\$75.00	0.00	\$75.00	Replace	Replace
			STICKER SG LOVE	1.00	\$75.00	0.00	\$75.00	Replace	Replace
			STICKER 60KM/H	1.00	\$5.00	0.00	\$5.00	Replace	Replace
Total					\$3,094.90		\$2,800.91		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

cm /
cm /
BCm /
cm /
nm /
nm /
nm /

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: