

Kenneth

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MY
 To Inspect Vehicle No: _____
 at Workshop m/s: Tong Luck
 of _____
 Insured: _____
 Policy No. 999993598
 Claims No. 5398421898SG
 Sum Insured: _____ Excess: 1700
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$120k
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 04 days Res.: Yes or No
 Lum Sum: 1.81 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SM7 3347P Yr Regn: 12, 17
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Mer C180 c.c. 1595
 Colour: M.L. Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 53596 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WDD 2050 40 2R 326808
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Mod: Nil / S/Rim / STD / R/Jm or _____
 Tyre Size: F: 225/50R17
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTS / PIR / BUMI /
 TOYO / YOKO or _____
 Front R/Bal. 8 mm Rear R/Bal. 8 mm
 L/Bal. 8 mm L/Bal. 8 mm
 D.O.A. 11/5/21 D.O.I. 4/6/2021
 Survey held at _____
 Des. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or
N/S/F
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
04/06/21 @ 4.23pm	revert to AIG via Merimen.
07/06/21 @ 9.29am	Kok Chong informed C/A via Merimen. part items no.3 to repair.
07/06/21 @ 12.17pm	Informed Candy C/A & ex:\$1700 & item no.3 to repair by email.
	Kenneth confirmed final fig.\$5461 (Red \$1922.75, 26%).

Date/Time, File Pass to? : Prell. Report
 1) 12/07 Typist : Final Report
 Date/Time, File Return to? _____
 2) _____

Days Of Repair: 4
 Resurvey No. of Trip: 1 Survey Fee: _____
 Transportation: _____
 Add Fee: : Site Insp (\$ _____)) \$ - RS. SI
 : Interview (\$ _____))
 : Tech Invs (\$ _____))
 : Weekend (\$ _____))
 Report Format : MER-OD
 Lump Sum / I.B.I: (\$ 5461)
 TOTAL _____



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.
78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT
TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :
CLAIM TYPE : OWN DAMAGE
ACCIDENT DATE : 11/05/2021

*Not Asstained
Mummy Bq pain
4 days*

ESTIMATE

NO : QUOT202105-000058(00)
DATE : 03/06/2021
POLICY NO : 999995580
VEH REG NO : SMZ3347P
MAKE/MODEL : MERCEDES BENZ C180
AVANTGARDE (R17 LED)
CHASSIS NO : WDD2050402R326808
ENGINE NO : 27491031121154
REG. DATE : 2017

Estimate Repair Cost to Vehicle No : SMZ3347P

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Headlamp assy - LH	1	1,850.00	1,850.00 ?
2 Headlamp bracket - LH	1	68.00	68.00 ?
3 Front fender - LH	1	590.00	590.00 ✓
4 Front fender inner shield - LH	1	98.00	98.00 ✓
5 Front fender inner shield clips - LH	20	5.50	110.00 ✓
6 Front bumper	1	1,080.00	1,080.00 ✓
7 Front bumper reinforcement	1	310.00	310.00 X
8 Front bumper side retainer - LH	1	38.00	38.00 ✓
9 Front bumper sensor	1	138.00	138.00 ✓
10 Front bumper sensor seals	6	8.00	48.00 ✓
11 Front bumper clips	15	5.50	82.50 ✓
			4,412.50
		Add 10%	441.25
			4,853.75
LABOUR			
12 To remove and refit front bumper sensor	1	100.00	100.00 60d
13 To check and rectify wiring system	1	80.00	80.00 20d
14 To panel beat and straighten LH front fender inner panel, LH front chassis frame, including replacement of parts and align where necessary, to refit and adjust the same	1	1,200.00	1,200.00 400d
15 To putty and spray paint on affected areas	1	800.00	800.00 400d
16 To reset and reprogramme headlamp fault code	1	350.00	350.00 ?
			2,530.00
		TOTAL	S\$ 7,383.75
		ADD GST @ 7%	516.86
		GRAND TOTAL	S\$ 7,900.61

SINGAPORE DOLLAR SEVEN THOUSAND NINE HUNDRED AND SIXTY-ONE ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 12/05/2021 01:03 (SGT)
Date of Accident 11/05/2021 16:00 (SGT)
Exact Location of Accident Yio Chu Kang Rd, Singapore
Additional Location Information YIO CHU KANG ROAD TURNING RIGHT TO ANG MO KIO AVE 3
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMZ3347P

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner DAIMLER FLEET MANAGEMENT SINGAPORE PTE LTD
Company Reg No 1XXXXX778Z
Email Address derrick.lee@daimler.com
Mobile Phone No (Phone) +65-68498118
Alternative Phone No (Office) +65-68498118

VEHICLE PARTICULARS

Manufacturer Mercedes
Model C180
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Private car
Transmission Auto
CC 1595

INSURANCE COMPANY

Name of Insurance Company AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage Comprehensive
Fleet Policy Yes
Policy Number 999995580
Cover Note Number -

DRIVER

Name of Driver ERIC LOH TIAN HON (ERIC LUO CANHONG)
NRIC No SXXXX748C

