



ESTIMATE TO REPAIR

VEHICLE NO. : SLC 3217 P
 MAKE : HONDA
 MODEL : VEZEL 1.5X CVT ABS D/AIRBAG 2WD 5DR
 YEAR : 2016
 CHASSIS NO : RU11116235

| |
|------------------|
| SURVEYOR NAME : |
| DATE OF SURVEY : |
| TIME OF SURVEY : |

DATE : 03.06.2021
 DATE OF ACCIDENT : 03.06.2021
 THIRD PARTY REF : SLL 5582 Z/ CHINA TAIPING

| No. | Parts Description/ Labour | Type | Unit Price | Nett Item Amt | Amount |
|--------|---|------|------------|---------------|--------------------|
| 1PC | REAR BUMPER | | | | \$ 532.10 |
| 2PCS | REAR BUMPER SIDE | | \$195.00 | | \$ 390.00 |
| 10PCS | REAR BUMPER CLIPS | | \$3.50 | | \$ 35.00 |
| 1PC | REAR END PANEL | | | | \$ 411.90 |
| 1PC | REAR END PANEL GARNISH | | | | \$ 92.30 |
| 1PC | REAR SPARE TYRE TOP COVER | | | | \$ 206.20 |
| 1PC | REAR SPARE TYRE SPONGE | | | | \$ 156.00 |
| 1PC | REAR SPARE TYRE LOWER COVER | | | | \$ 190.00 |
| 1PC | TAIL GATE | | | | \$ 1,050.00 |
| 1PC | TAIL GATE EMBLEM | | | | \$ 43.00 |
| 1PC | TAIL GATE LOCK | | | | \$ 157.10 |
| 1PC | TAIL GATE RUBBER | | | | \$ 101.30 |
| 1PC | REAR WIND SCREEN MOULDING | | | | \$ 120.00 |
| 1PC | REAR EXHAUST SILENCER BOX | | | | \$ 528.00 |
| | | | | | \$ 4,012.90 |
| | LESS 20% | | | | \$ 802.58 |
| | | | | | \$ 3,210.32 |
| 1 SET | REAR BUMPER SENSOR | SN | | | \$ 200.00 |
| 1PC | REAR WIND SCREEN SEALANT | SN | | | \$ 40.00 |
| | TO PUTTY & SPRAY PAINT | | | | \$ 800.00 |
| | TO TRANSFER TAIL GATE FITTING | | | | \$ 80.00 |
| | TO REMOVE & REFIX REAR WINDSCREEN GLASS | | | | \$ 100.00 |
| | TO ANTI RUST | | | | \$ 80.00 |
| | LABOUR CHARGES | | | | \$ 700.00 |
| TG/YLH | TOTAL | | | | \$ 5,210.32 |

Lim Tan Motor Pte Ltd
 Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
 Tel:65-64520893 Fax:65-64589127 Email: edmund@LTM.sg Website : www.LTM.sg
 Co.Reg No.199307277D GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd