

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: FBK9308Y
at Workshop m/s: 13HH
of _____
Insured: GMS 1409J
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: FBK9308Y Yr Regn: 30/3/16
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or 3-wheeler
Make: ADIWA / AR3 200 c.c. 171
Colour: Blue A/C: Insured / Std / NI / NA
Sp.Reading: 33161 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: RGV TC40AAGA000004
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or other
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Tyre Size: F: 120/70-14
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Timsen
Front _____ Rear _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. _____ mm L/Bal. 6 mm
D.O.A. 24/5/24 D.O.I. 4/6/24
Survey held at _____

Bal. or Market Value: 9k
IDAC Accident Rport: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: days Res.: Yes or No
Lum Sum: % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS LTA 3781
Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
N/S Frt.
The UIC / Chassis frame / Body Structure affected due to collision.

Date: _____ Person Contacted: _____

Date / Time Action / Instruction NHT 5219

Date/Time, File Pass to? : Preli. Report
1) : Final Report
Date/Time, File Return to?

Days Of Repair: _____
Resurvey No. of Trip: _____
Survey Fee: _____
Transportation: _____

2) Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____) Photos
 : Tech. Invs (\$ _____) Others
 : Weekend (\$ _____)
Report Format : _____
Lump Sum / I.B.I: (\$) _____)
TOTAL _____



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

EQ INSURANCE COMPANY LIMITED
22 GEMMILL LANE
SINGAPORE 069257

ATTN: MOTOR CLAIMS DEPT

VEHICLE NO. : FBK9308Y
MAKE/MODEL : ADIVA / AR3 200

*not actual
Here
h/s \$
3 days.
4/8/21
Edu. Mr. Athu & repair*

NO. : 38487

DATE : 28/05/2021
CLAIM NO. : 11737
POLICY NO. :
FROM : RAYMOND

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BALL SET P/N: 48814 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$19.00	19.00 ✓
2	BALL SET SMALL P/N: 48813 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$14.00	14.00 ✓
3	BOTTOM DUST GUARD P/N: 48811 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$27.00	27.00 ✓
4	COVER COMPARTMENT TANK P/N: 51182 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$42.00	42.00 ✓
5	FORK FRONT ASSY COMPLETE P/N: 48812 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$845.00	845.00 ✓
6	HEADLIGHT LH P/N: 49385 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$217.00	217.00 ✓
7	HEADLIGHT RH P/N: 51547 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$217.00	217.00 ✓
8	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	* Supply/Install	6.00	\$63.00	378.00 ✓
9	LEG SHIELD P/N: 51969 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$147.00	147.00 ✓

*38487 *

bizSAFE₃



S/N	Description	Action	Qty	Unit Price	Amount
10	RACE STRG TOP COND P/N: 48807 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	28.00
11	SEAL DUST STRRING CONE P/N: 53166 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$7.00	7.00
12	SHIELD ASSY FRONT METALLIC (BLUE) P/N: 49437 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$528.00	528.00
13	TOP CAP <i>steering cone top</i> P/N: 48808 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	28.00
14	TOP CAP <i>steering cone bottom</i> P/N: 48810 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	28.00
15	TRANSPORT CHARGES (MOTORCYCLE) OVERSIZED P/N: 45837 - BIKE TOWED BACK TO BHH		1.00	\$98.00	98.00
SUB TOTAL					\$2,623.00
GST @ 7 %					\$183.61
GRAND TOTAL (SGD)					\$2,806.61

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

*38487 *

*bizSAFE*₃



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	623M
Vehicle Details	
Vehicle No.:	FBK9308Y
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Jun 2021
Vehicle Make:	ADIVA
Vehicle Model:	AR3 200 3-WHEELER CVT
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	MA812015
Chassis No.:	RGVTC40AAGA000004
Maximum Power Output:	-
Open Market Value:	\$4,470.00
Original Registration Date:	30 Mar 2016
First Registration Date:	30 Mar 2016
Transfer Count:	1
Actual ARF Paid:	\$671.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Mar 2026
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,503.00
COE Rebate Amount:	\$3,781.00
Total Rebate Amount:	\$3,781.00

The information contained herein is correct as at 05 Jun 2021

OK