



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
TAN KOK QUAN PARTNERSHIP 1 WALLICH STREET #07-02 GUOCO TOWERSINGAPORE 078881			Ref: CS/LAW21006413/Utf3e2	
			Date: 16/07/2021	
			Code: L021	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	SLS 6199D	Veh. Inspected	SJX 8562Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	TWK/DAQ/pkf/1729.20	Excess (\$)	0.00	
Assign From	TEO WENG KIE	Assign Date	04/06/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PREVIA (A)	c.c	2362	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	JTEGD54M30A020942	Colour	BLACK	
Odometer	69522 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R18	MICHELIN	5 mm	
L/H Front Tyre	225/50 R18	MICHELIN	5 mm	
R/H Rear Tyre	225/50 R18	MICHELIN	5 mm	
L/H Rear Tyre	225/50 R18	MICHELIN	5 mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	18/08/2020	Inspection Date	15/06/2021	
Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	