

ASS. REC. BY:

Steve

CS/CTI 21206416/EVC

ASSIGNMENT

From:

Date:

Estimated Cost:

☒ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No. DMPCSNW00063852101

Claims No. SNM21D203173/C01/TANKL

Sum Insured:

Excess:


1000

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Est. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Cum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SDN 26005

Yr Regn:

2/4/19

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Lexus ES 250

c.s. 9487

Colour:

White

A/O: Insured / Std / NI / N

Sp. Reading

27201

T/Radio: Insured / Std / NI / N

Eng/No:

C/No:

IT-181151702002576

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrakes: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModl: NII / ☒ R/Rim / ☐ STD A/Rim or

Tyre Size:

F:

235/45R18

R:

11

BS: ☒ BUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

3/6/21

D.O.I.

7/8/21

Survey held at

Boon Motors

Des. of Damages: ☒ Fr / ☐ Rear / ☐ O/S / ☐ N/S / ☐ UIC / ☐ Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MV-152K

26/6/21

Final fig \$17,585.80 confirmed by email (Red 20,403.40,53%)

Date/Time, File, Pass to?



: Prel. Report



: Final Report

Date/Time, File Return to?

26/6/21-Typist

Days Of Repair: 8

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee:



: Site Insp

(\$

\$ + RS. 61



: Interview

(\$

: Police



: Tech. Inve

(\$

: Others



: Weekend

(\$

: TOTAL

Prepared by: Merimen

Net Sum / L.P.I. / \$17,585.80



Borneo Motors

Inchcape

Co. Reg No. : 1967000862
GST Reg No. : MR-8500000-9
No 2 Pandan Crescent
Singapore 128462. Tel no : 6631 1388




ESTIMATE

Account Details				Account No.		Customer Details			
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept				S1000003 / ICC11		Ms Ker Lay Tin 32 Sturdee Road #24-10 Singapore 207853 Mobile: 90055795			
				Document No. 0					
				Document Date 04/06/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2018	AXZA10R	AEZGB S1	02/04/2019	SDN2600J	0	19682	61UL/SDN2600J/030621		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTHB11B1702002526		A25A0230974	60	Carine Yeo C L	-/-/- 0.00 -/-/-		0.00		
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES POLICY NO.: ACC DATE: TOW/DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:						50 ✓	
2	B	BP-LAB3 TO REMOVE ALL NECESSARY PARTS TO ENABLE REPAIRING AND STRAIGHTEN ON BONNET, FRONT BUMPER, FRONT SUPPORT AND FIX NEW PARTS			866 X1			866 4330.00	
3	B	BP-RES3 TO SPRAY PAINT ON WHOLE FRONT PORTION INCLUDE SUPPORT			742 X2			1484 4452.00	
4	Z	BP-SLANT SUPPLY BONNET SEALANT (NETT)						100.00 X	
5	Z	BP-SLANT SUPPLY FRONT SUPPORT SEALANT (NETT)						100.00 X	
6	B	BP-LAB3 TO REMOVE AND RE-INSTALL AIR COND CONDENSER, RADIATOR ETC TO ENABLE REPAIR (NETT)						866.00 X	
For & on behalf of		Customer's Signature		Charge Summary		Total			
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less			
						Amount Due			

Customer Copy



Borneo Motors



o. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No 2 Pandan Crescent
Singapore 128462, Tel no : 6631 1388

ESTIMATE

Account Details			Account No.		Customer Details			
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICC11		Ms Ker Lay Tin 32 Sturdee Road #24-10 Singapore 207853 Mobile: 90055795			
			Document No. 0					
			Document Date 04/06/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2018	AXZA10R	AEZGB S1	02/04/2019	SDN2600J	0	19682	61UL/SDN2600J/030621	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTHB11B1702002526		A25A0230974	60	Carine Yeo C L	--/--/----		0.00	--/--/----
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount		
7	B	BP-LAB3 TO REMOVE AND TRANSFER FRONT PARKING SENSOR TO NEW BUMPER, REPLACE IF DAMAGE (NETT)				216.50 ✓		
8	B	BP-LAB3 TO REMOVE AND RE-INSTALL BOTH HEADLAMPS TO CHECK FOR DAMAGES, REPLACE IF DAMAGE (NETT)				216.50 ✓		
9	L	BP-LPO SUPPLY FRONT NO PLATE AND CASING - m/s (NETT)				96.00 ✓		
10	B	BP-ECU3 TO RESET ECU AND REPROGRAMME (NETT)				216.50 ✓		
11	T	BP-MISC1 SHOULD THE ABOVE VEHICLE BE SUBJECT TO TOTAL LOSS OR TOW OUT BY INSURANCE COMPANY OR BY THE OWNER PRIOR TO THE REPAIR A 6% OF THE QUOTATION PRICE WILL BE IMPOSED AS ADMIN CHARGES TO A MAX OF \$1000 + TOWING CHARGES IF APPLICABLE.						
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total	
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less	
							Amount Due	

Customer Copy



Borneo Motors



Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No 2 Pandan Crescent
 Singapore 128462, Tel no : 6631 1388

ESTIMATE

Account Details		Account No.	Customer Details				
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICC11	Ms Ker Lay Tin 32 Sturdee Road #24-10 Singapore 207853 Mobile: 90055795				
		Document No.					
		0					
		Document Date					
		04/06/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	AXZA10R	AEZGB S1	02/04/2019	SDN2600J	0	19682	61UL/SDN2600J/030621
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTHB11B1702002526		A25A0230974	60	Carine Yeo C L	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
12	Z	BP-MISC2 A DAILY STORAGE CHARGE AT THE RATE OF S\$25/- PER DAY WILL COMMENCE 7 DAYS AFTER ESTIMATE DATE. THESE CHGS WILL NOT APPLY IF REPAIRS ARE UNDERTAKEN BY BORNEO MOTORS.					
13	1	L52611-33330 ABSORBER, FR BUMPER	1.00	112.40		112.40	
14	2	L52148-33040 BRACKET, FR BUMPER	1.00	503.30		503.30	
15	3	L52021-33240 REINFORCEMENT	1.00	909.60		909.60	
16	4	L52620-50010 CHAMBER ASSY,	1.00	790.30		790.30	
17	5	L52618-33090 ABSORBER, FR BUMPER,	1.00	281.30		281.30	
18	6	T53879-33030 RETAINER, FR FENDER	6.00	12.20		73.20	
19	7	L52146-33110 BRACKET, FR BUMPER	1.00	9.20		9.20	
20	8	T90189-06237 GROMMET, SCREW	2.00	1.80		3.60	
21	9	T90467-07049 23 CLIP	4.00	2.40		9.60	
22	0	L52119-3T958 COVER, FR BUMPER	1.00	1093.10		1093.10	
23	1	L52542-33010 SEAL, FR BUMPER, CTR	1.00	92.50		92.50	
24	2	L52114-33520 BRACKET, FR BUMPER	1.00	161.10		161.10	
25	3	L53106-33010 GARNISH SUB-ASSY,	1.00	222.70		222.70	
26	4	L53105-33010 GARNISH SUB-ASSY,	1.00	222.70		222.70	
27	5	L52128-33919 COVER, FR BUMPER	1.00	54.20		54.20	

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Sublet	
		Lubrication/Fluid	
		Others	Amount Due

Customer Copy



Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No 2 Pandan Crescent
Singapore 128462, Tel no : 6631 1388

ESTIMATE

Account Details				Account No.		Customer Details			
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept				S1000003 / ICC11		Ms Ker Lay Tin 32 Sturdee Road #24-10 Singapore 207853 Mobile: 90055795			
				Document No. 0					
				Document Date 04/06/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2018	AXZA10R	AEZGB S1	02/04/2019	SDN2600J	0	19682	61UL/SDN2600J/030621		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTHB11B1702002526		A25A0230974	60	Carine Yeo C L	--/--/----		0.00	--/--/----	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount	
28	6	L52127-33905	COVER, FR BUMPER	X	1.00	54.20		54.20	
29	7	L53114-33050	GRILLE, RADIATOR,		1.00	199.30		199.30	
30	8	L52116-33100	SUPPORT, FR BUMPER		1.00	43.00		43.00	
31	9	L52115-33110	SUPPORT, FR BUMPER		1.00	43.00		43.00	
32	0	T47749-33030	CLIP, PIN HOLD		6.00	8.60		51.60	
33	1	L89348-50130	RETAINER, ULTRASONIC		2.00	19.20		38.40	
34	2	L53101-33670	GRILLE SUB-ASSY,		1.00	1660.70		1660.70	
35	3	L53112-33510	GRILLE, RADIATOR,		1.00	223.40		223.40	
36	4	L53301-33260	HOOD SUB-ASSY		1.00	2962.10		2962.10	
37	5	L53510-33512	LOCK ASSY, HOOD		1.00	170.10		170.10	
38	6	L53203-33180	SUPPORT SUB-ASSY,		1.00	306.00		306.00	
39	7	L53202-33110	SUPPORT SUB-ASSY,		1.00	306.00		306.00	
40	8	L53205-33902	SUPPORT SUB-ASSY,		1.00	428.90		428.90	
41	9	T57104-33080	MEMBER SUB-ASSY, FR		1.00	226.40		226.40	
42	0	L53295-33140	SEAL, COOL AIR		1.00	322.10		322.10	
43	1	T53299-33020	PLATE, COOL AIR		1.00	26.00		26.00	
44	2	T90467-07217	CLIP		10.00	2.50		25.00	
45	3	L53141-53031	GARNISH, RADIATOR		1.00	1082.90		1082.90	
46	4	L81185-33F21	UNIT, HEADLAMP		1.00	3702.20		3702.20	
47	5	L81145-33F21	UNIT, HEADLAMP		1.00	3702.20		3702.20	
For & on behalf of				Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd									
				Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less	
								Amount Due	

Customer Copy

Borneo Motors



Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No 2 Pandan Crescent
Singapore 128462. Tel no. 6631 1388

ESTIMATE

Account Details			Account No.		Customer Details												
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICC11		Ms Ker Lay Tin 32 Sturdee Road #24-10 Singapore 207853 Mobile: 90055795												
			Document No. 0														
			Document Date 04/06/2021														
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks										
2018	AXZA10R	AEZGB S1	02/04/2019	SDN2600J	0	19682	61UL/SDN2600J/030621										
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On										
JTHB11B1702002526		A25A0230974	60	Carine Yeo C L	--/--/----		0.00 --/--/---- 0.00										
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount									
48	6	L89341-33220 A3 SENSOR, ULTRASONIC, ?			2.00	490.80		981.60									
49	7	L89341-33220 C4 SENSOR, ULTRASONIC, ?			2.00	488.00		976.00									
50	8	L884A0-33040 CONDENSER ASSY, ?			1.00	2803.70		2803.70									
51	9	L16400-25130 RADIATOR ASSY ?			1.00	2363.10		2363.10									
52	0	S08889-80102 COOLANT, SLLC&&& ?			2.00	79.50		159.00									
<p><i>Handwritten:</i> Stere C LKK) 00-AL AL 7/6/21, 19.00am Excess - \$1990 5 dys P/P, Ry Bel sy Ry Bel sy</p>																	
<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after repainting To display damaged part(s) for survey Parts prices are subject to confirm Third party surveys on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company 				<p>Customer's Signature</p> <p>Signature: _____ Date: _____</p> <p>Please acknowledge receipt of vehicle</p>		<p>Charge Summary</p> <table border="1"> <tr> <td>Parts</td> <td>27,395.70</td> </tr> <tr> <td>Labour</td> <td>10,497.50</td> </tr> <tr> <td>Sublet</td> <td>96.00</td> </tr> <tr> <td>Lubrication/Fluid</td> <td>0.00</td> </tr> <tr> <td>Others</td> <td>0.00</td> </tr> </table>		Parts	27,395.70	Labour	10,497.50	Sublet	96.00	Lubrication/Fluid	0.00	Others	0.00
Parts	27,395.70																
Labour	10,497.50																
Sublet	96.00																
Lubrication/Fluid	0.00																
Others	0.00																
<p>For & on behalf of Borneo Motors (Singapore) Pte Ltd</p> <p><i>Signature:</i> _____</p>				<p>Total 37,989.20</p> <p>GST 7.00% 2,659.24</p> <p>Less 0.00</p> <p>Amount Due 40,648.44</p>													

Customer Copy