



方商昭噴漆 POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.
Tel: 6453 7511 Fax: 6453 8046 Email: sitti1@singnet.com.sg Regn. No. 05396600K

ANG CHENG GUAN
Apt Blk 189 Bishan Street 13
#09-435
Singapore 570189

*Not Withheld
1/1 Day &
Resurvey After Painting
3 days*

Dear sir
Estimate cost of repair to vehicle no. SLW 1594H

To supply

1. Head lamp left
2. Head lamp bracket left
3. Front bumper
4. Front bumper retainer x2
5. Front bumper reinforcement
6. Front bumper sensor
7. Front bumper fog lamp cover
8. Front fender
9. Front grille top
10. Front grill bottom

<i>Cur</i>	1,923.50	<i>✓</i>
<i>Sm</i>	145.00	<i>X</i>
<i>New Cur</i>	801.70	<i>✓</i>
<i>Sm</i>	60.00	<i>X</i>
<i>R</i>	321.80	<i>X</i>
<i>new</i>	350.00	<i>2001</i>
<i>Sm</i>	205.00	<i>X</i>
<i>R</i>	506.00	<i>X</i>
<i>Cur</i>	351.90	<i>✓</i>
<i>Cur</i>	386.80	<i>✓</i>

201

Labour charges

Panel beating
Spray painting
Rust proofing
Total

	900.00	<i>2501</i>
	800.00	<i>2201</i>
<i>new</i>	80.00	<i>X</i>
	6,831.70	

Your faithfully

ALBERT POON

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: