



POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.
Tel: 6453 7511 Fax: 6453 8046 Email: sitti1@singnet.com.sg Regn. No. 05396600K

ANG CHENG GUAN
Apt Blk 189 Bishan Street 13
#09-435
Singapore 570189

Not Withheld
11 Days @ 2650h
Returning After Pains
3 days

Dear sir
Estimate cost of repair to vehicle no. SLW 1594H

To supply

1. Head lamp left *1859.20*
2. Head lamp bracket left
3. Front bumper *762.20*
4. Front bumper retainer x2
5. Front bumper reinforcement
6. Front bumper sensor
7. Front bumper fog lamp cover
8. Front fender
9. Front grille top
10. Front grill bottom

<i>Cur</i>	1,923.50	<i>✓</i>
<i>Sm</i>	145.00	<i>X</i>
<i>New Cur</i>	801.70	<i>✓</i>
<i>Sm</i>	60.00	<i>X</i>
<i>R</i>	321.80	<i>X</i>
<i>New</i>	350.00	<i>2001</i>
<i>Sm</i>	205.00	<i>X</i>
<i>R</i>	506.00	<i>X</i>
<i>Cur</i>	351.90	<i>✓</i>
<i>Cur</i>	386.80	<i>✓</i>

201

Labour charges

Panel beating
Spray painting
Rust proofing
Total

	900.00	<i>2501</i>
	800.00	<i>2201</i>
<i>rr</i>	80.00	<i>X</i>
	6,831.70	

Your faithfully

ALBERT POON

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: