

AUTOPROBE CONSULTANTS

To: SMRT AUTOMOTIVE SERVICES PTE LTD
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

Our Ref.: SVY190900088
Date: 20/03/2020

AUTOMOBILE INSPECTION REPORT

1. **SURVEY TYPE:** THIRD PARTY
Assignment Date: 10/09/2019
Vehicle Inspected: FBM-8437-D
Insured Vehicle: SHF- 335-H
Date of Accident: 07/09/2019
Repairer / Survey at: REVOLOGY BIKES PTE LTD

Your Reference: TAX/09/19/2027
Policy Excess: -
Surveyed / Assessed Date: 11/09/2019
Resurvey Date: 13/09/2019, 16/09/2019

2. **VEHICLE PARTICULARS:**
Make & Model: HONDA CB150R MANUAL
Registration Date: 23/04/2018
Engine Capacity: 149
Chassis No.: MLHKC288XJ5013829
Engine No.: KC32E0013829

General Condition: FAIR
Colour: BLACK
Odometer (km): 270
Steering: IN ORDER
Brake: IN ORDER

3. **TYRE CONDITION:**

	Size	Make	Thread Depth (%)
FRONT	110/70-17	DUNLOP	70
REAR	150/60-17	DUNLOP	70

4. **DESCRIPTION OF DAMAGES:**
The motorcycle sustained damages mainly at the rear portion.

AUTOPROBE CONSULTANTS

Your Ref.: TAX/09/19/2027
Our Ref.: SVY190900088

Vehicle No.: FBM-8437-D
Date of Accident: 07/09/2019

5. ADJUSTMENT SUMMARY:

Original Estimate: -
Revised: -
Final Adjustment: -
Estimated Repair Duration: 2.00 Working Days

6. ESTIMATED VALUE (at time of accident):

Market Value: \$9,800.00
LTA Rebate: \$5,641.00 (as at 12/09/2019)
Nett: \$4,159.00

7. INSPECTIONS

Despite our request, the repairer did not provide us with the repair estimate.

- Pre-repair inspection conducted on 11/09/2019.
- Dismantled parts inspection conducted on 13/09/2019.
- Post-repair inspection conducted on 16/09/2019.

The Inspection was conducted on a "Without Prejudice" basis.

Assessor: SAMUEL PHUN

AUTOPROBE CONSULTANTS

Your Ref.: TAX/09/19/2027
Our Ref.: SVY190900088

Vehicle No.: FBM-8437-D
Date of Accident: 07/09/2019




Photograph 2 of 78



Photograph 1 of 78



Photograph 4 of 78




Photograph 3 of 78


AUTOPROBE CONSULTANTS

Your Ref.: TAX/09/19/2027
Our Ref.: SVY190900088


Vehicle No.: FBM-8437-D
Date of Accident: 07/09/2019



Photograph 6 of 78



Photograph 5 of 78



Photograph 8 of 78




Photograph 7 of 78

AUTOPROBE CONSULTANTS


Your Ref.: TAX/09/19/2027
Our Ref.: SVY190900088

Vehicle No.: FBM-8437-D
Date of Accident: 07/09/2019

Photograph 10 of 78



Photograph 9 of 78



Photograph 12 of 78




Photograph 11 of 78



AUTOPROBE CONSULTANTS

Your Ref.: TAX/09/19/2027
Our Ref.: SVY190900088


Vehicle No.: FBM-8437-D
Date of Accident: 07/09/2019




Photograph 14 of 78



Photograph 13 of 78



Photograph 16 of 78




Photograph 15 of 78


AUTOPROBE CONSULTANTS

Your Ref.: TAX/09/19/2027
Our Ref.: SVY190900088


Vehicle No.: FBMA-B437-D
Date of Accident: 07/09/2019



Photograph 18 of 78



Photograph 17 of 78



Photograph 20 of 78




Photograph 19 of 78

AUTOPROBE CONSULTANTS

Your Ref.: TAX/09/19/2027
Our Ref.: SVY190900088

Vehicle No.: FBM-8437-D
Date of Accident: 07/09/2019


Photograph 22 of 78




Photograph 21 of 78



Photograph 24 of 78



Photograph 23 of 78



AUTOPROBE CONSULTANTS

Your Ref.: TAX/09/19/2027

Our Ref.: SVY190900088


Vehicle No.: FBM-8437-D

Date of Accident: 07/09/2019


Photograph 26 of 78



Photograph 25 of 78



Photograph 28 of 78



Photograph 27 of 78




AUTOPROBE CONSULTANTS

Your Ref.: TAX/09/19/2027
Our Ref.: SVY190900088

Vehicle No.: FBM-8437-D
Date of Accident: 07/09/2019



Photograph 30 of 78



Photograph 29 of 78



Photograph 32 of 78



Photograph 31 of 78

AUTOPROBE CONSULTANTS

Your Ref.: TAX/09/19/2027
Our Ref.: SVY190900088

Vehicle No.: FBM-8437-D
Date of Accident: 07/09/2019


Photograph 34 of 78



Photograph 33 of 78



Photograph 36 of 78



Photograph 35 of 78



AUTOPROBE CONSULTANTS


Your Ref.: TAX/09/19/2027
Our Ref.: SVY190900088

Vehicle No.: FBM-8437-D
Date of Accident: 07/09/2019


Photograph 38 of 78



Photograph 37 of 78



Photograph 40 of 78



Photograph 39 of 78




AUTOPROBE CONSULTANTS

Your Ref: TAX/09/19/2027
Our Ref: SVV190900088

Vehicle No.: FBM 8447-D
Date of Accident: 07/09/2019




Photograph 42 of 73



Photograph 41 of 73



Photograph 44 of 73



Photograph 43 of 73

AUTOPROBE CONSULTANTS

Your Ref.: TAX/09/19/2027
Our Ref.: SVY190900088

Vehicle No.: FBM-8437-D
Date of Accident: 07/09/2019

Photograph 46 of 78




Photograph 45 of 78



Photograph 48 of 78



Photograph 47 of 78



AUTOPROBE CONSULTANTS

Your Ref.: TAX/09/19/2027
Our Ref.: SVY190900088

Vehicle No.: FBM-8437-D
Date of Accident: 07/09/2019

Photograph 50 of 78




Photograph 49 of 78



Photograph 52 of 78



Photograph 51 of 78



AUTOPROBE CONSULTANTS

Your Ref.: TAX/09/19/2027
Our Ref.: SVY190900088

Vehicle No.: FBM-8437-D
Date of Accident: 07/09/2019

Photograph 54 of 78



Photograph 53 of 78



Photograph 56 of 78



Photograph 55 of 78




AUTOPROBE CONSULTANTS

Your Ref.: TAX/09/19/2027
Our Ref.: SVY190900088

Vehicle No.: FBM-8437-D
Date of Accident: 07/09/2019



Photograph 58 of 78



Photograph 57 of 78



Photograph 60 of 78




Photograph 59 of 78

AUTOPROBE CONSULTANTS

Your Ref.: TAX/09/19/2027
Our Ref.: SVY190900088

Vehicle No.: FBM-8437-D
Date of Accident: 07/09/2019


Photograph 62 of 78



Photograph 61 of 78



Photograph 64 of 78



Photograph 63 of 78




AUTOPROBE CONSULTANTS

Your Ref.: TAX/09/19/2027
Our Ref.: SVY190900088

Vehicle No.: FBM-B437-D
Date of Accident: 07/09/2019




Photograph 66 of 78



Photograph 65 of 78



Photograph 68 of 78




Photograph 67 of 78

AUTOPROBE CONSULTANTS


Your Ref.: TAX/09/19/2027
Our Ref.: SVY190900088

Vehicle No.: FBM-8437-D
Date of Accident: 07/09/2019

Photograph 70 of 78




Photograph 69 of 78



Photograph 72 of 78



Photograph 71 of 78



AUTOPROBE CONSULTANTS

Your Ref.: TAX/09/19/2027
Our Ref.: SVY190900088

Vehicle No.: FBM-8437-D
Date of Accident: 07/09/2019



Photograph 74 of 78



Photograph 73 of 78



Photograph 76 of 78




Photograph 75 of 78

AUTOPROBE CONSULTANTS

Your Ref.: TAX/09/19/2027
Our Ref.: SVY190900088

Vehicle No.: FBM-8437-D
Date of Accident: 07/09/2019

Photograph 78 of 78



Photograph 77 of 78

