

VEHICLE DAMAGE ASSESSMENT REPORT

To: Zulkiflee Bin Aris

CC: Team Work Garage Pte Ltd
 53 Ubi Ave. 1 #01-24
 Paya Ubi Industrial Park
 Singapore 408934

REFERENCES

Ref No	: 2021/3015	Date of Report	: 29/3/2021
Claim Type	: Third Party	Date of Request	: 31/3/2021
Third party vehicle	: SLS1326L	Date of Accident	: 26/3/2021
Insured Vehicle	:	Date of Inspection	: 31/3/2021
Your Reference No	: -		

DAMAGED VEHICAL PARTICULARS

Registration Plate No	: SLS1326L	Engine Modification	: NIL
Model / Make	: Mitsubishi Lancer	Pre-accident damage	: NIL
Colour	: Red	General Condition	: Good
Manufacturing Year	: 2007	General Paint Work	: Good
Engine No	: 4A910073825	Steering	: Serviceable
Engine Capacity	: 1500cc	Handbrake	: Serviceable
Chassis No	: JMYSRCY2A8U004239	Footbrake	: Serviceable
Odometer No	: 258770		
Transmission	: Auto		

TYRES CONDITION

Front Right		Rear Left	
Make	: Michelin	Make	: Michelin
Size	: 225/45 r17 4	Size	: 225/45 r17 4
Front Left		Rear Right	
Make	: Michelin	Make	: Michelin
Size	: 225/45 r17 4	Size	: 225/45 r17 4

The above millimetres represent the remaining life of tyre treads

VEHICAL REPAIR COST

<u>Descriptions</u>	<u>Repairer (\$\$)</u>	<u>Difference (\$\$)</u>	<u>Adjuster (\$\$)</u>
Parts	16,655.50		13,852.00
Labour	8,270.00		7,030.00
Calculated Cost (\$\$) :	24,925.50	4,043.50	20,882.00

Recommended Lump Sum Repair Cost (\$\$)	: <u>16,700.00</u>
Estimate Repair Duration	: <u>18</u>
Survey Inspection At	: Team Work Garage Pte Ltd
Survey Inspection Address	: 53 Ubi Ave. 1 #01-23/24 Paya Ubi Industrial Park Singapore 408934

Our Reference :2021/3015

Your Reference:

Vehicle Number : SLS1326L

S/N	Qty	Description	Condition	Repairer Estimate (\$\$)	Our Assessment (\$\$)	
		<u>Parts</u>				
1	1pcs	Front bumper	Dented	985.00	985.00	832
2	1pcs	Front bumper centre grille	Dented	87.00	87.00	/
3	1pcs	Front bumper lower spoiler	Deformed	971.00		
4	2pcs	Front bumper fog lamp @426/pcs	Serviceable	852.00	-	
5	2pcs	Front bumper fog lamp cover @36/pcs	Serviceable	72.00	-	
6	2pcs	Front bumper side retainer @15/pcs	Torn	30.00	30.00	/
7	2pcs	Front bumper side bracket @45/pcs	Torn	90.00	90.00	/
8	1pcs	Front bumper top beam	Dented	84.00	84.00	/
9	1pcs	Front bumper re enforcement	Dented	390.00	390.00	/
	1pcs	Front bumper top seal	Necessary	28.00	28.00	X SVC
11	1pcs	Front grille	Crack	307.00	307.00	/
12	1pcs	Front grille logo	Necessary	57.00	57.00	/
13	1pcs	Bonnet	Dented	809.00	809.00	758
14	2pcs	Bonnet hinges @58/pcs	Serviceable	116.00	-	
15	1pcs	Bonnet inner lock	Dented	67.00	67.00	/
16	1pcs	Support panel	Dented	681.00	681.00	580
17	1pcs	Support panel top garnish	Deformed	136.00	136.00	101
18	1pcs	Brace panel	Dented	267.00	267.00	91
19	2pcs	Headlamp @292/pcs	Holder Torn	1,584.00	1,584.00	1382
20	1pcs	Horn	Dented	79.00	79.00	X SVC
21	1pcs	Condenser	Dented	937.00	937.00	/
22	1pcs	Radiator	Dented	1,116.00	1,116.00	761
23	1pcs	Radiator fan assy.	Holder Torn	480.00	480.00	261
24	1pcs	Rear bumper	Dented	815.00	815.00	700
25	2pcs	Rear bumper reflector @22/pcs	Crack	44.00	44.00	/
26	1pcs	Rear bumper lower spoiler	Deformed	710.00	710.00	/
27	2pcs	Rear bumper side retainer @15/pcs	Torn	30.00	30.00	/
28	1pcs	Rear bumper re enforcement	Dented	210.00	210.00	/
29	2pcs	Rear bumper re enforcement bracket @45/pcs	Dented	90.00	90.00	/
	1pcs	Boot lid	Dented	693.00	693.00	/
31	1pcs	Boot lid logo	Necessary	47.00	47.00	/
32	1pcs	Boot lid emblem "turbo"	Necessary	52.00	52.00	/
33	1pcs	Boot lid emblem "mivec"	Necessary	48.00	48.00	/
34	1pcs	Boot lid emblem "lancer"	Necessary	52.00	52.00	/
35	1pcs	Boot lid emblem "ex"	Necessary	39.00	39.00	/
36	1pcs	Boot lid third brake lamp	Broken	336.00	336.00	/
37	2pcs	Boot lid reflector @336/pcs	Broken	672.00	672.00	/
38	1pcs	Boot lid spoiler	Serviceable	826.00	-	/
39	1pcs	Boot lid inner lock	Dented	67.00	67.00	/
40	1pcs	Boot lid inner rubber	Kinded	84.00	84.00	/
41	1pcs	Boot lid inner trim	Torn	183.00	183.00	/
42	2pcs	Boot lid hinges @84/pcs	Serviceable	168.00	-	/
43	2pcs	Boot lid absorber @	Serviceable	96.00	-	/
44	2pcs	Boot lid stopper @	Serviceable	48.00	-	/
45	2pcs	Taillamp @320/pcs	Base Broken	640.00	640.00	/
46	2pcs	Taillamp panel @86/pcs	Dented	86.00	172.00	X R
47	1pcs	Rear lh fender	Dented	988.00	988.00	X R
48	1pcs	Rear lh fender inner trim	Torn	223.00	223.00	/
49	1pcs	Rear rh fender	Dented	988.00	988.00	822
50	1pcs	Rear rh fender inner trim	Torn	223.00	223.00	/
51	1pcs	Rear end panel	Dented	506.00	506.00	420

52	1pcs	Rear end panel inner trim	Deformed	149.00	149.00	✓
53	1pcs	Spare tyre panel	Dented	521.00	521.00	XR
54	1pcs	Spare tyre panel top board	Serviceable	155.00	-	
55	1pcs	Rear windscreen moulding	Necessary	180.00	180.00	✓
Total				20,194.00	16,976.00	(3529
Less 25%				5,048.50	4,244.00	
Parts Sub Total				15,145.50	12,732.00	10146.75

Special Nett

56	1sets	Coolant	Necessary	80.00	50.00	20
57	1pcs	Front no plate	Dented	80.00	80.00	70
58	1sets	Front bumper clips	Necessary	80.00	50.00	30
59	1sets	Rear Bumper clips	Necessary	80.00	50.00	30
60	1sets	Boot lid inner trim clips	Necessary	80.00	50.00	20
61	1sets	Rear lh fender inner trim clips	Necessary	80.00	50.00	20
62	1sets	Rear rh fender inner trim clips	Necessary	80.00	50.00	20
63	1sets	Boot lid sealant	Necessary	80.00	60.00	XNN
64	1sets	Rear lh fender sealant	Necessary	80.00	60.00	XNN
65	1sets	Rear rh fender sealant	Necessary	80.00	60.00	30
66	1sets	Rear end panel sealant	Necessary	100.00	60.00	30
67	1sets	Spare tyre panel sealant	Necessary	100.00	60.00	XNN
68	1sets	Rear windscreen sealant	Necessary	80.00	60.00	50
69	1sets	Rear windscreen inner seal	Necessary	50.00	50.00	20
70	1pcs	Rear no plate	Dented	80.00	80.00	70
71	1sets	Reverser sensor	Dented	300.00	250.00	200
Total				1,510.00	1,120.00	

Labour

1	To check wiring sytsem.(Front)	60.00	50.00	30
2	To reprogramme after the accident repair works .	150.00	120.00	XNN
3	To r&r condenser and re charge air con gas.	150.00	150.00	120
4	To cut and weild on support panel. To panel beat and straighten on front both wheel housing. To r&r front bumper, bonnet, headlamp, front grille and others attachments.	1,000.00	800.00	600
5	To putty and respray on front bumper, bonnet, front both fenders, front lower spoiler and accident affected areas.	1,000.00	950.00	700
6	To check wiring sytsem.(Rear)	60.00	50.00	30
7	To r&r inner trim for hot work repair.	100.00	60.00	50
8	To transfer boot lid attachments.	100.00	80.00	60
9	To r&r rear windscreen glass.	150.00	150.00	120
10	To r&r fuel tank for hot work repair.	150.00	120.00	X
11	To r&r rear exhaust pipe.	150.00	100.00	70
11	To cut and weild on rear end panel, spare tyre panel. To panel beat on rear both fender. To r&r rear bumper,boot lid and others attachments.	3,000.00	2,600.00	1600

12	To respray on rear bumper, rear both fender, boot lid, rear end panel, spare tyre panel and accident affected area.	2,000.00	1,600.00	1200
13	To carry out body cavity preservation	200.00	200.00	150
	Labour Total	8,270.00	7,030.00	
	Sub Total (labour and parts)	24,925.50	20,882.00	

Adjustment / Recommendations

Note: For Lump Sum Repair

The workshop has agreed to undertake the repair on a Lump Sum Basis, and/or use of ex-stock/reconditioned parts whichever is possible (having taken into consideration to repair instead of replacements).

The final adjusted Lump Sum contract amount is **S\$16,700**.

Under normal circumstances, the repair period would be about **18** working days.

15486.75

20% : 12350

Net = \$8000


14 Days.

DESCRIPTION OF DAMAGE

At the time of inspection, this vehicle sustained damages to the **Front and Rear Portion**.

Front bumper, bonnet, support panel dented, headlamp holder torn, condenser, radiator dented. Rear bumper, boot lid, rear fender, spare tyre panel dented, taillamp, boot lid lamp broken etc.

Please see attached scheduled details.



SPECIAL REMARKS

We have not authorised repair. Under normal circumstances, estimated **18** working days are required to repair the vehicle.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Inspection Report and photographs.

Anthony
Automotive Appraiser
MSAAA

Disclaimer:

This survey was conducted by Precise Appraiser Pte Ltd without prejudice basis and we do not authorized repair. Report by Precise Appraiser Pte Ltd is deemed as confidential and provided for the use of clients and appointed agent. *We have inspected thoroughly each and every item on the repairer's estimate against the actual damages found on the vehicle.* All findings and recommendations are listed accordingly and final decision of settlement to your good selves parts thereof accordingly and final. No liability shall be attached to Precise Appraiser Pte Ltd therefore.

BIDDED CARPLATE NUMBERS FOR SALE

Find and buy your favourite car plate number here!

SGC8888M

ST
SEA
NO

Mitsubishi Lancer

Price Range

Depreciation

> 10 year(

Vehicle Type



A

Home » Used Cars » Car Empire Automobiles Pte Ltd » Mitsubishi Lancer 1.5A GLX (COE till 08/2023)

Mitsubishi Lancer 1.5A GLX (COE till 08/2023)

Overview

Financial

Accessories

Similar

Research

Photos

Map



Price \$19,200

Depreciation ⑦ \$8,690 /yr

Reg Date 27-Aug-2008
(2yrs 2mths 15days COE left)

Mileage N.A.

Manufactured ⑦ 2008

Road Tax ⑦ \$889 /yr

Transmission Auto

Dereg Value ⑦ \$7,552 as of today (change)

OMV ⑦ \$14,531

COE ⑦ \$17,099

ARF ⑦ \$12,612

Engine Cap 1,499 cc

Power 80.0 kW (107 bhp)

Curb Weight ⑦ 1,313 kg

No. of Owners ⑦ 4

Type of Vehicle Mid-Sized Sedan

Features

Responsive 1.5L Powerful And Fuel Efficient DOHC MIVEC Engine, Reliable 4 Speed Automatic Transmission, Dual SRS Airbags, Climatic Aircon. View specs of the Mitsubishi Lancer EX (2008-2017)

Accessories

Varis Version Full Body Kit, Customize Duck Boot Lip, Soundstream Tweeter, Lufi Gauge, Sport Rims, Ksport High Low Soft Hard Coilover And Many More.

Description


Excellent Condition, Well Maintain With A Striking Outlook. Full Body Kit And Stock Condition. Wear And Tear Replaced, View To Believe Its Condition STA Evaluation Welcome. Full Loan & Bank Loan With An Attractive Rates. Contact Our Friendly Sale Team Today. Don't Miss This Beauty. This Is A Consignment Unit.

Category

COE Car

Star

Compare



Shortlist

Compare

Report

More

Seller Information

Car Empire Automobiles Pte Ltd

39 vehicles for sale. 54 sold in past 3 mths

210 Turf Club Road Lot A19/A20

Car Mall @ The Grandstand

Tel: 69097310

Search cars nearby



Zac

87495321

Edmund

90529225

Soon

97379527

Ben

88668682

Singapore Reckless
Drivers Part X

What's in your car?!

Very bad fuel
consumption ?

Mitsubishi Lancer Price Range Depreciation > 10 year(s) Vehicle Type

Home » Used Cars » Gen Y Automobile » Mitsubishi Lancer EX 1.5A GLS Sports Sunroof (COE till 09/2022)

Mitsubishi Lancer EX 1.5A GLS Sports Sunroof (COE till 09/2022)

[Overview](#) Financial Accessories Similar Research Photos Map

Price	\$12,800		
Depreciation ?	\$9,820 /yr	Reg Date	21-Dec-2007 (1yr 3mths 19days COE left)
Mileage	N.A.	Manufactured ?	2007
Road Tax ?	\$958 /yr	Transmission	Auto
Dereg Value ?	\$5,749 as of today (change)	OMV ?	\$16,970
COE ?	\$22,041	ARF ?	\$18,667
Engine Cap	1,499 cc	Power	80.0 kW (107 bhp)
Curb Weight ?	1,313 kg	No. of Owners ?	More than 6
Type of Vehicle	Mid-Sized Sedan		

Features

Powerful And Fuel Efficient 1.5L DOHC MIVEC Engine, Smooth 4 Speed Auto Trans, Dual SRS Airbags, Climatic Aircon, Auto Headlights, Sunroof! View specs of the Mitsubishi Lancer EX (2008-2017)

Accessories

Full Bodykit! Factory Fitted Audio System, Factory Fitted Leather Seats, Multi Function Steering Wheel, Upgraded 17" Sports Rims.

Description

Monthly At \$670 Only! Free 1 Year Engine And Gearbox Extended Warranty! Bank / Inhouse Loan Available! Only Exterior Mods For A Sporty Looking Ride! No Mods To Software! Hassle Free Drive Till End Of COE With No Headaches! Wait No Further To Grab This Beautiful Ride Back Home! Welcome All Kinds Of Trade-In. Come And Experience Our Passionate Pre-Owned Car Services.

Category

COE Car

Status

Available for sale. Shortlist this car to get alerted whenever the price or availability changes.

Resources

[Compare](#) [Valuation](#)[Shortlist](#)
[More](#)[Compare](#)[Report](#)

Seller Information

Gen Y Automobile

44 vehicles for sale. 21 sold in past 3 mths

18 Sin Ming Lane #05-08
Midview City
[Search cars nearby](#)

Scord Ho 91894999
Roman 97251960