

HIN LUNG WORKSHOP

Blk 1008 Bukit Merah Lane 3 #01-20, S'pore 159722. Tel: 68583000 Fax: 64760075
Website: www.hinlung.com.sg GST Regn. No: M2-0065859-X

Your Ref:
Our Ref : 0721/06/21
M/s : INDIA INTERNATIONAL INSURANCE P.LTD
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711
Attn : MOTOR CLAIM DEPARTMENT

Page: 1
Date: 04/06/2021

Dear Sir/Madam,

ACCIDENT REPAIR ON : SJL294L - CROSSROAD 1.8 0
INSURED : HESAMUDIN BIN TAIB
DATE OF ACCIDENT : 30/05/2021
YOUR INSURED VEH NO: GBE8187S

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED:-

		S\$	S\$	S\$
REPLACEMENT OF PARTS				
1 FRONT BUMPER <i>de</i>	1 @	2,800.00	2,800.00	
2 FRONT SIDE RETAINER LEFT <i>X</i>	1 @	84.00	84.00	
3 FRONT SIDE RETAINER RIGHT <i>X</i>	1 @	84.00	84.00	
4 FACE, RIGHT BUMPER SIDE <i>sea</i>	1 @	160.00	160.00	
5 BUMPER CLIPS <i>re</i>	10 @	5.50	55.00	
6 BUMPER UNDERCOVERAGE <i>X</i>	1 @	320.00	320.00	
7 FRONT FENDER WHEEL ARCH <i>sea</i>	1 @	410.00	410.00	
Total				3,913.00

LABOUR CHARGES

- 1 REPLACE NEW PARTS, REMOVE/REFIT ALL
- 1 ATTACHMENT PARTS TO FACILITATE REPAIR
- 1
- 2 SPRAY PAINT ON THE EFFECTED AREAS
- 2 WITH 2K PAINT
- 2
- 3 CHECK WIRING AND PROPER FUNCTIONING

Nett Total Before GST

~~500.00~~ 400

~~900.00~~ 200

80.00 *X*

5,393.00

Yours faithfully,

(Workshop Manager)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resul
Hp 900 10068
3 days
4/5
08/06/21 @ 1000
Reg after repair