

HIN LUNG WORKSHOP

Blk 1008 Bukit Merah Lane 3 #01-20, S'pore 159722. Tel: 68583000 Fax: 64760075
Website: www.hinlung.com.sg GST Regn. No: M2-0065859-X

Frc

F Your Ref:

Page: 1

Date: 04/06/2021

Our Ref : 0721/06/21

M/s : INDIA INTERNATIONAL INSURANCE P.LTD

64 CECIL STREET

#04/#05 IOB BUILDING

SINGAPORE 049711

Attn : MOTOR CLAIM DEPARTMENT

Dear Sir/Madam,

ACCIDENT REPAIR ON : SJL294L - CROSSROAD 1.8 0

INSURED : HESAMUDIN BIN TAIB

DATE OF ACCIDENT : 30/05/2021

YOUR INSURED VEH NO: GBE8187S

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED:-

REPLACEMENT OF PARTS

- 1 FRONT BUMPER *de*
- 2 FRONT SIDE RETAINER LEFT *X su*
- 3 FRONT SIDE RETAINER RIGHT *X su*
- 4 FACE, RIGHT BUMPER SIDE *su*
- 5 BUMPER CLIPS *re*
- 6 BUMPER UNDERCOVERAGE *X su*
- 7 FRONT FENDER WHEEL ARCH *su*

	S\$	S\$	S\$
1 @ 2,800.00	2,800.00	1200	1755
1 @ 84.00	84.00	X	
1 @ 84.00	84.00	X	
1 @ 160.00	160.00	X	
10 @ 5.50	55.00	X	
1 @ 320.00	320.00	X	
1 @ 410.00	410.00	340	
			1404
			3,913.00

Total

LABOUR CHARGES

- 1 REPLACE NEW PARTS, REMOVE/REFIT ALL
- 1 ATTACHMENT PARTS TO FACILITATE REPAIR
- 1
- 2 SPRAY PAINT ON THE EFFECTED AREAS
- 2 WITH 2K PAINT
- 2
- 3 CHECK WIRING AND PROPER FUNCTIONING

1464	
600	
2004	
200	
1603.20	
418-1,600	
500.00	400
900.00	200
80.00	X nn
	600
	5,393.00

Nett Total Before GST

Yours faithfully,

(Workshop Manager)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/alter spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resur
Hp 900 10068
3 days
4/8
08/06/21 @ 1000
Res after repair