

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Alfred Toh

Date: 11 Jun 2021

Preliminary Advice

Insured : SLV938L

Vehicle No

TP Vehicle : SLK5155D
No

Accident Date : 28/05/2021

Make : BMW 116D

Assignment Date : 09/06/2021

Date of : 10/06/2021

Inspection

Est. Duration of : 2
Repair

Inspection At : ACCORD AUTO SERVICES PTE LTD (HQ)
10 ANG MO KIO IND PARK 2A #03-11, AMK AUTO POINT
SINGAPORE 568047

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,807.80
Revised Amount	:S\$	676.65
Check Items (Estimated)	:S\$	2,231.80
Total	:S\$	2,908.45

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$

Margin for Repair :S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :