



# 友尼摩多公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/00D

LKK

DATE: 13/07/2021 OUR REF: UAPL1469  
REPAIR ESTIMATE YOUR VEHICLE VOLVO XC60 NO: SFH2588U

- 1 REAR BUMPER FACE (TOP) *Replaced*
- 2 REAR BUMPER FACE SENSOR *Replaced*
- 1 REAR BUMPER LOWER SPOILER *Replaced*
- 1 REAR BUMPER INNER GARNISH *Replaced*
- 2 REAR BUMPER SIDE RETAINERS *New*
- 2 REAR BUMPER REFLECTOR *Replaced*
- 1 REAR BUMPER REINFORCEMENT *New*
- 10 REAR BUMPER CLIPS *New*
- 2 REAR TAILLAMPS LOWER BRACKET *New*
- 1 REAR BOOT ASSY *Replaced*
- 1 REAR BOOT LOCK *Replaced*
- 1 REAR BOOT LOCK INNER SENSOR *New*
- 1 REAR BOOT STRIKER *New*
- 1 REAR BOOT VOLVO EMBLEM *New*
- 1 REAR BOOT XC60 EMBLEM *New*
- 1 REAR BOOT T5 EMBLEM *New*
- 1 REAR BOOT WEATHERSTRIP *New*
- 1 REAR TAIL END PANEL *Replaced*
- 1 REAR TAIL END PANEL LINING *New*
- 1 REAR WINDSCREEN MOULDING *New*

LESS 10%.....

|    |           |      |
|----|-----------|------|
| \$ | 2,011.00  | 1830 |
| \$ | 644.00    | ✓    |
| \$ | 1,224.00  | 950  |
| \$ | 311.00    | ✓    |
| \$ | 362.00    | ✓    |
| \$ | 380.00    | ✓    |
| \$ | 897.00    | ✓    |
| \$ | 80.00     | 50   |
| \$ | 244.00    | ✓    |
| \$ | 3,986.00  | ✓    |
| \$ | 534.00    | ✓    |
| \$ | 448.00    | ✓    |
| \$ | 38.00     | ✓    |
| \$ | 155.00    | ✓    |
| \$ | 88.60     | ✓    |
| \$ | 87.60     | ✓    |
| \$ | 221.00    | ✓    |
| \$ | 1,012.00  | ✓    |
| \$ | 312.00    | ✓    |
| \$ | 156.00    | ✓    |
| \$ | 13,191.20 |      |
| \$ | 1,319.12  |      |
| \$ | 11,872.08 |      |

## SPECIAL NETT:-

- 1 REAR NUMBER PLATE/HOLDER *New*
- 1 REAR GLASS DAM RUBBER

|    |       |   |
|----|-------|---|
| \$ | 50.00 | ✓ |
| \$ | 60.00 | ✓ |

## LABOUR CHARGES:-

- TO DISM/RENEW REAR REVERSE SENSOR
- TO DISM/REWIRE REAR DAMAGED PORTION
- TO DISM/REFIX REAR WINDSCREEN GLASS
- TO RESET ECU AFTER REPAIR
- TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS
- TO PUTTY AND RESPRAY DAMAGED PORTION
- TO DISM REAR SEAT, ROOF LINING IN REPAIR

|    |           |     |
|----|-----------|-----|
| \$ | 100.00    | 50  |
| \$ | 180.00    | 30  |
| \$ | 180.00    | ✓   |
| \$ | 280.00    | 150 |
| \$ | 1,000.00  | 500 |
| \$ | 1,000.00  | 500 |
| \$ | 180.00    | ✓   |
| \$ | 14,902.08 |     |

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 5757.18

L/s: A.G.K.

04 Days