

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: AJ.tk.6795.2019.KC.PD Date: 21st June 2021

Our Ref: CS1/LAW21006435/Gqf3e2

M/s Crossborders LLC

133 New Bridge Road #23-03 Chinatown Point Singapore 059413

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: GZ 9397B

INSURED VEHICLE: XD 5181Y ACCIDENT DATE: 17/05/2018

We thank you for your instruction on 07/06/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GZ 9397B from M/s Quantum Risk Management.
- b) Singapore Accident Statement and Police Report of Vehicles XD 5181Y and GZ 9397B.
- c) Colour damaged vehicle photographs of GZ 9397B.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : GZ 9397B

Make & Model : Toyota Hiace Manual Chassis Number : JTFHT02P200001131

Year of Registration : 2006 Engine Capacity : 2982 cc

- 2. We recommend that the repairs of the entire damage require about 14 (Fourteen) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.