

Your Ref: AC.2020.041

Date: 21st June 2021

Our Ref: CS1/LAW21006435/Gqf3e2

M/s Sompo Insurance Singapore PL

C/O : Chey LLC

20 Havelock Road #02-47

Singapore 059765

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: GZ 9397B**INSURED VEHICLE: XD 5181Y****ACCIDENT DATE: 17/05/2018**

We thank you for your instruction on 07/06/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GZ 9397B from M/s Quantum Risk Management.
- b) Singapore Accident Statement and Police Report of Vehicles XD 5181Y and GZ 9397B.
- c) Colour damaged vehicle photographs of GZ 9397B.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: GZ 9397B
Make & Model	: Toyota Hiace Manual
Chassis Number	: JTFHT02P200001131
Year of Registration	: 2006
Engine Capacity	: 2982 cc

2. We recommend that the repairs of the entire damage require about 14 (Fourteen) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.