



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2106066

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 30/08/2021
Reference CC6/CTI21006437/Uea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SLJ 9185X
Insured Veh. PC 1206L
Claim No. SNM21D203286/C02
Policy No. DMB1SNW00001442100
Accident Date 22/05/2021
Inspection Date 07/06/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21006437/Uea3q2 Date: 30/08/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PC 1206L	Veh. Inspected	SLJ 9185X	
Policy No.	DMB1SNW00001442100	Coverage (\$)	0.00	
Claim No.	SNM21D203286/C02	Excess (\$)	0.00	
Assign From		Assign Date	07/06/2021	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN QASHQAI (A)	c.c	1197	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	SJNFEAJ11U1713001	Colour	BROWN	
Odometer	32870 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R17	FALKEN	6 mm	
L/H Front Tyre	215/60 R17	FALKEN	6 mm	
R/H Rear Tyre	215/60 R17	FALKEN	6 mm	
L/H Rear Tyre	215/60 R17	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/05/2021	Inspection Date	07/06/2021	
Survey held at	T K LEE AUTOMOTIVE PTE LTD NO. 1 KAKI BUKIT AVE 6 #02-47 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 9185X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT GRILLE	CRACKED	577.60	577.60
1	FRONT GRILLE EMBLEM 'LOGO'	SCRATCHED	79.90	79.90
1	FRONT BUMPER	DENTED / DEFORMED	751.20	751.20
1	FRONT BUMPER FOAM	NOT NECESSARY	240.90	-
2	FRONT BUMPER SIDE RETAINER RH/LH @\$42.00	NOT NECESSARY	84.00	-
	LESS 10% DISCOUNT		-173.36	-140.87
			1,560.24	1,267.83
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT NUMBER PLATE WITH CASING (SN)	BENT	50.00	40.00
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	45.00	45.00
			95.00	85.00
<u>LABOUR</u>				
	TO KNOCK OUT DENT AND REPLACE ACCIDENT PARTS.		300.00	150.00
	TO SPRAY PAINTING ON ACCIDENT PORTION .		300.00	200.00
			600.00	350.00
GRAND TOTAL			2,255.24	1,702.83
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,300.00

Report Ref No. CC6/CTI21006437/Uea3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLJ 9185X

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLJ 9185X

RE-INSPECTION

