

ASS. REC. BY:

TGuin

REF:

CC4/A1921006440/Bpa3

Hsiao Jong

## ASSIGNMENT

From:

Date: 7/6/2021

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMN 9069R

at Workshop m/s

Deam Auto pro

of 160 Sin Ming Dr # 01-14

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

67,000/2

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

8

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMN 9069R

Yr Regn: 30/8/2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Fit 1.3GF

c.c 1317

Colour

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

30620

T/Radio: Insured / Std / NI / NA

Eng/No:

L13B1452071

C/No:

4K31343757

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ~~order~~ / Jammed / Leaked / Burnt orBrake: ~~order~~ / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195/55/15

R: 195/55/15

BS / DUN / EXNOVA / GY / FS / LIZA / MC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

4/6/2021

D.O.I.

7/6/2021

Survey held at

Deam Auto pro

Des. of Damages: Frt / ~~Rear~~ / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Part by Part repair

#5168.38

Recommended COR is ~~\$5,128~~ on part by part basis

TGuin

15/6/2021

MV 67,000/2

PV 28,216/2

NV 38,784/2

TGuin

15/6/2021

Date/Time, File Pass to?

☐

Preli. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Report Format:

Lump Sum / L.B.B.C

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

SJE : \_\_\_\_\_  
 Date of Survey : \_\_\_\_\_  
 Date of ReSurvey: \_\_\_\_\_ After-Paint: \_\_\_\_\_  
 Contacts : \_\_\_\_\_

Vehicle Nos : **SMN 9069 R**  
 Model : Honda Fit  
 Year : \_\_\_\_\_  
 Chassis No : \_\_\_\_\_

**\* AGREED Cost Of Repair and Repair Day/s with SJE \***

Amount: \_\_\_\_\_

Working Day: \_\_\_\_\_

| Nos. | PARTS                        | Qty | Unit S\$                    | TOTAL S\$                     |
|------|------------------------------|-----|-----------------------------|-------------------------------|
| 1    | Tailgate                     | 1   | \$ 1,085.20                 | \$ <del>845.20</del> 1,085.20 |
| 2    | Tailgate logo                | 1   | \$ 86.20                    | \$ <del>45.60</del> 86.20     |
| 3    | Tailgate emblem 'Fit'        | 1   | \$ 83.40                    | \$ <del>35.00</del> 83.40     |
| 4    | Tailgate inner lock          | 1   | \$ 310.50                   | \$ <del>131.80</del> 310.50   |
| 5    | Tailgate inner lock striker  | 1   | \$ 48.90                    | \$ <del>48.90</del>           |
| 6    | Tailgate reflector           | 2   | \$ 583.20                   | \$ <del>1,166.40</del>        |
| 7    | Tailgate weatherstrip        | 1   | \$ 186.20                   | \$ <del>148.20</del> 186.20   |
| 8    | Tailgate inner trim board    | 1   | \$ 486.00                   | \$ <del>285.00</del> 486.00   |
| 9    | Tailgate inner handle        | 1   | \$ 56.20                    | \$ <del>56.20</del>           |
| 10   | Tailgate outer garnish       | 1   | \$ 263.20                   | \$ <del>263.20</del>          |
| 11   | Tailgate windscreen moulding | 1   | \$ 132.60                   | \$ <del>70.00</del> 132.60    |
| 12   | Rear bumper                  | 1   | \$ 976.40                   | \$ <del>485.00</del> 976.40   |
| 13   | Rear bumper side retainer    | 2   | \$ <del>21.97</del> 87.50   | \$ <del>43.94</del> 175.00    |
| 14   | Rear bumper bracket          | 2   | \$ 75.60                    | \$ <del>151.20</del>          |
| 15   | Rear bumper centre garnish   | 1   | \$ 103.00                   | \$ <del>65.00</del> 103.00    |
| 16   | Rear bumper side garnish     | 2   | \$ <del>38.00</del> 286.40  | \$ <del>76.00</del> 572.80    |
| 17   | Rear end panel               | 1   | \$ 865.70                   | \$ <del>314.00</del> 865.70   |
| 18   | Rear end panel top garnish   | 1   | \$ 186.50                   | \$ <del>79.04</del> 186.50    |
| 19   | Spare tyre panel             | 1   | \$ 881.70                   | \$ <del>881.70</del>          |
| 20   | Spare tyre panel top board   | 1   | \$ 250.00                   | \$ <del>250.00</del>          |
| 21   | Spare tyre panel insulator   | 1   | \$ 188.60                   | \$ <del>188.60</del>          |
| 22   | Taillamp                     | 2   | \$ <del>244.60</del> 686.00 | \$ <del>489.20</del> 1,372.00 |
| 23   | Taillamp lower bracket       | 2   | \$ 85.00                    | \$ <del>170.00</del>          |
|      |                              |     | Parts Sub Total :           | \$ 9,797.70                   |
|      |                              |     | Discount :                  | \$ 1,959.54                   |
|      |                              |     | <b>PARTS TOTAL :</b>        | <b>\$ 7,838.16</b>            |

Parts Sub Total : \$ 9,797.70  
 Discount : \$ 1,959.54  
**PARTS TOTAL : \$ 7,838.16**

20%

@ 20%  
 3,122.98  
 624.60  
 2,498.38

| Nos.                 | SPECIAL NETT                           | Qty | Unit S\$  | TOTAL S\$   |      |
|----------------------|----------------------------------------|-----|-----------|-------------|------|
| 1                    | Sundries                               | 1   | \$ 80.00  | \$ 80.00    | NNX  |
| 2                    | Tailgate sealant                       | 1   | \$ 100.00 | \$ 100.00   | NECV |
| 3                    | Tailgate emblem 'MUGEN'                | 1   | \$ 40.00  | \$ 40.00    | NECV |
| 4                    | Tailgate reflector clips               | 2   | \$ 50.00  | \$ 100.00   | NNX  |
| 5                    | Tailgate inner trim board clips        | 1   | \$ 50.00  | \$ 50.00    | NECV |
| 6                    | Tailgate outer garnish clips           | 1   | \$ 50.00  | \$ 50.00    | NECV |
| 7                    | Tailgate windscreen clips              | 1   | \$ 50.00  | \$ 50.00    | NNX  |
| 8                    | Tailgate windscreen sealant            | 1   | \$ 100.00 | \$ 100.00   | NECV |
| 9                    | Tailgate windscreen primer and cleaner | 1   | \$ 80.00  | \$ 80.00    | NNX  |
| 10                   | Tailgate windscreen seal               | 1   | \$ 60.00  | \$ 60.00    | NECV |
| 11                   | Rear bumper clips                      | 1   | \$ 50.00  | \$ 50.00    | NECV |
| 12                   | Rear bumper centre garnish clips       | 1   | \$ 50.00  | \$ 50.00    | NNX  |
| 13                   | Rear bumper side garnish clips         | 2   | \$ 50.00  | \$ 100.00   | NNX  |
| 14                   | Rear number plate w/casing             | 1   | \$ 80.00  | \$ 80.00    | NNX  |
| 15                   | Rear bumper reverse sensor             | 2   | \$ 200.00 | \$ 400.00   | SCV  |
| 16                   | Rear end panel sealant                 | 1   | \$ 100.00 | \$ 100.00   | NECV |
| 17                   | Rear end panel top garnish clips       | 1   | \$ 50.00  | \$ 50.00    | NECV |
| 18                   | Taillamp seal                          | 2   | \$ 60.00  | \$ 120.00   | NNX  |
| 19                   | Taillamp clips                         | 2   | \$ 50.00  | \$ 100.00   | NNX  |
| SPECIAL NETT TOTAL : |                                        |     |           | \$ 1,760.00 |      |

500.00

| Nos.           | LABOUR                         | S\$       |          |
|----------------|--------------------------------|-----------|----------|
| 1              | R&R tailgate component         | \$ 80.00  | 150.00   |
| 2              | R&R tailgate windscreen        | \$ 120.00 | 250.00   |
| 3              | R&R rear bumper reverse sensor | \$ 60.00  | 100.00   |
| 4              | Check wiring                   | \$ 30.00  | 100.00   |
| 5              | Upholstery                     | \$        | 200.00   |
| 6              | Panel beating                  | \$ 100.00 | 1,400.00 |
| 7              | Rust proofing                  | \$ 80.00  | 200.00   |
| 8              | Spray painting                 | \$ 800.00 | 1,400.00 |
| LABOUR TOTAL : |                                | \$        | 3,800.00 |

2,170.00

Part by Part repair  
Repair day 8

PARTS TOTAL : \$ 7,838.16  
SPECIAL NETT TOTAL : \$ 1,760.00  
LABOUR TOTAL : \$ 3,800.00  
GRAND TOTAL : \$ 13,398.16

Parts 2498.38  
SN 500.00  
Labour 2,170.00  
5168.38

\$5168.38

COR

TQM Min

15/6/2021

**LKK Auto Conc** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: