



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2300149

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 10/01/2023
Reference CC6/CTI21006441/Apa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. XE 227C
Insured Veh. GBE 9048D
Claim No. SNM21D203285
Policy No. DMCVSNW00073302000
Accident Date 04/06/2021
Inspection Date 09/06/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21006441/Apa3q2 Date: 10/01/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBE 9048D	Veh. Inspected	XE 227C
	Policy No.	DMCVSNW00073302000	Coverage (\$)	0.00
	Claim No.	SNM21D203285	Excess (\$)	0.00
	Assign From		Assign Date	09/06/2021
2. Vehicle Particulars & Condition				
	Make & Model	HINO FY1ETMM	c.c	12913
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	FY1ETM10012	Colour	WHITE
	Odometer	192248 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	295/80 R22.5	GT RADIAL	8 mm
	L/H Front Tyre	295/80 R22.5	GT RADIAL	8 mm
	R/H Rear Tyre	295/80 R22.5	GT RADIAL	8 mm
	L/H Rear Tyre	295/80 R22.5	GT RADIAL	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	04/06/2021	Inspection Date	09/06/2021
	Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 227C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT N/S WHEEL HUB	NOT NECESSARY	2,370.60	-
	LESS 25% DISCOUNT		-592.65	-
			1,777.95	-
	<u>SPECIAL NETT ITEMS</u>			
1	REAR N/S ALUMINIUM (SN)	DENTED	1,300.00	780.00
1	REAR ALUMINIUM BRACKET (SN)	BENT	300.00	200.00
10	REAR ALUMINIUM BRACKET NUT (SN)	NECESSARY	50.00	20.00
2	TYRES (SN)	CUT (1 PCS ONLY)	1,600.00	480.00
1	GREASE (SN)	NOT NECESSARY	100.00	-
1	FRONT N/S RIM (SN)	NOT NECESSARY	1,067.20	-
			4,417.20	1,480.00
	<u>LABOUR</u>			
	TO REMOVE AND REPLACE DAMAGED PARTS.		400.00	350.00
	TO SPRAY PAINT.		200.00	180.00
	TO REMOVE AND REPLACE FRONT N/S UNDERCARRIAGE .	NOT NECESSARY	600.00	-
	TO CHECK WHEEL ALIGNMENT.	NOT NECESSARY	240.00	-
			1,440.00	530.00
	GRAND TOTAL		7,635.15	2,010.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,600.00

Report Ref No. CC6/CTI21006441/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. XE 227C

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. XE 227C

RE-INSPECTION

