



TRANS EUROKARS PTE LTD

ELROKARS GROUP

ESTIMATE COST OF REPAIRS

CHINA TAIPING INSURANCE P/L 3 ANSON ROAD #18-00 SPRINGLEAF TOWER SINGAPORE 079909		NAME : ADDRESS : TEL :		WIP : 35X03 EXCESS : DATE : 19-May-21	
ATTN : MOTOR CLAIMS FAX :					
VEH NO :	SMG8507L	DATE IN :		CONTACT PERSON :	RONALD
CHASSIS NO :	JM6BN24A8K0251665	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA 3	DATE REG.:		POLICY NO.:	

NATURE OF WORKS

Parts Description

NO	DESCRIPTION	PARTS NO	QTY	1st	Supp	REVISED	PRICE
1	REAR BUMPER	MB63C-50-221AB8	1				\$ 997.50
2	BRACKET, REAR BUMPER	MKD53-50-251	1			de ✓	\$ 5.40
3	RETAINER RHS, REAR BUMPER	MBHN9-50-2H1C	1			?	\$ 37.40
4	RETAINER LHS, REAR BUMPER	MBHN9-50-2J1C	1			?	\$ 37.40
5	GUARD LHS, REAR BUMPER	MB63D-50-371	1			?	\$ 30.60
6	PROTECTOR, REAR BUMPER	MBHN9-50-369	1			?	\$ 58.80
7	TOWING HOOK COVER RHS	MB63B-50-EK1 BB	1		X	X	\$ 15.80
8	TOWING HOOK COVER LHS	M863B-50-EL1 BB	1			X	\$ 15.80
9	TAPE, PROTECTOR	MGS1D-50-EM1A	2			rec ✓	\$ 17.20
10	REAR BUMPER REFLECTOR RHS	MD350-51-5M0E	1			X	\$ 53.00
11	REAR BUMPER REFLECTOR LHS	MD350-51-5L0E	1			X	\$ 53.00
12	REAR BUMPER REINFORCEMENT	MB45C-50-260	1			X	\$ 564.20
13	CLIP, REAR BUMPER	MBGV4-56-145	2			rec ✓	\$ 5.80
14	FASTENER, REAR BUMPER	MB45A-56-146A	2			rec ✓	\$ 6.00
15	RETAINER, SENSOR	MKD47-67-UC5A27	4			rec ✓	\$ 72.80
16	SENSOR, ULTRASONIC	MGMK6-67-UC1 27	2			X	\$ 361.80
17	SENSOR, ULTRASONIC	MKD47-67-UC1 27	2			X	\$ 407.20
18	RIVET, REAR BUMPER	MEA01-50-037	2			rec ✓	\$ 16.00
19	GROMMET, REAR BUMPER	MBHN1-50-021A	4			rec ✓	\$ 10.80
20	T/LAMP GASKET RHS, BODY	MBHP1-51-153	1			rec ✓	\$ 22.00
21	T/LAMP GASKET LHS, BODY	MBHP1-51-163	1			rec ✓	\$ 22.00
22	ANTENNA, LF	MKD47-67-6NXA	1			uh X	\$ 111.10
23	CLIP, ANTENNA	MKD45-67-6NYA	1			uh X	\$ 2.70

TOTAL PARTS

\$ 2,924.30

TOTAL PARTS COST

\$ 2,924.30

SUPPLEMENTARY

NO	DESCRIPTION	PARTS NO	QTY	1st	Supp	REVISED	PRICES
----	-------------	----------	-----	-----	------	---------	--------

GRAND TOTAL	\$	-	\$	-
-------------	----	---	----	---

TRANS EUROKARS PTE LTD

Authorised Signature

REMARKS:
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tayfun 97495749
w/p 7/6/21
P/P Resurvey before paint
Ozeleg
Tayfun@lkkauto.com