

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department \ Motor Claim

Estimate No: EST2100144
Date: 03 Jun 2021
Veh Reg No: SMN305T
Make/Model: TOYOTA VIOS 1.5E
AUTO
Chasis No: MR2B23F3001179987
Reg. Date: 23/07/2019
Your Ref No: SDG4390M

Claim Type: Third Party
Accident Date: 02/06/2021
TP Veh Reg No: SDG4390M

Xiao Tony.

Estimate Repair Cost to Vehicle No :SMN305T

Quantity	Description	List Price	Amount
		SS	SS
List Price			
1	1 PC REAR BUMPER <i>Dented</i>	482.20 ✓	
2	1 PC REAR BUMPER REINFORCEMENT <i>Dented</i>	316.60 ✓	
3	2 PCS REAR BUMPER SIDE RETAINER RH <i>Neu</i>	327.80 <i>75</i>	
4	2 PCS REAR BUMPER RETAINER (SMALL) <i>RH Dented</i>	145.40 <i>65</i>	
5	1 PC REAR BUMPER REFLECTOR - LH <i>Cracked</i>	179.80 ✓	
6	1 PC REAR FENDER INNER TRIM RH <i>Neu</i>	355.90 +	
7	1 PC TAIL LAMP - RH <i>Cracked</i>	397.10 ✓	
8	1 PC REAR PANEL <i>Dented</i>	628.60 ✓	
9	1 PC REAR PANEL TRIM <i>Neu</i>	282.20 +	
10	1 PC BOOT LID LOGO	52.20 +	
11	1 PC BOOT LID "VIOS" EMBLEM	43.60 ✓	
12	1 PC BOOT LID "E" EMBLEM	38.40 +	
13	1 PC BOOT LID RUBBER	166.40 ✓	
		3,416.20	
Less 25%		854.05	2,562.16
Special Net			
14	2 PCS "L" PLATE BRACKET <i>Best</i>	70.00 <i>50</i>	
15	1 SET REAR BUMPER CLIPS <i>Neu</i>	40.00 <i>30</i>	
16	1 SET REAR BUMPER STICKER <i>Neu</i>	280.00 <i>180</i>	
17	1 PC "L" PLATE <i>Best.</i>	80.00 <i>50</i>	
18	1 PC REAR FENDER STICKER RH <i>Neu</i>	290.00 <i>280</i>	
19	1 SET REAR FENDER INNER TRIM CLIPS RH <i>Neu</i>	60.00 +	
20	1 SET REAR PANEL TRIM CLIPS <i>Neu</i>	40.00 +	
21	1 PC BOOT LID NUMBER '625' STICKER <i>Neu</i>	35.00 +	
		895.00	895.00
Labour			
22	1 TO CHECK WIRING	50.00 <i>30</i>	
23	1 TO REPLACE STICKER	100.00 +	
24	1 TO SPRAY UNDERSEAL	100.00 <i>60</i>	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST 201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party
Accident Date: 02/06/2021
TP Veh Reg No: SDG4390M

Estimate No: EST2100144
Date: 03 Jun 2021
Veh Reg No: SMN305T
Make/Model: TOYOTA VIOS 1.5E
AUTO
Chasis No: MR2B23F3001179987
Reg. Date: 23/07/2019
Your Ref No: SDG4390M

Estimate Repair Cost to Vehicle No :SMN305T

Quantity	Description	List Price	Amount
25	1 (REAR) TO SPRAY PAINTING	1,200.00 1540	800 800
26	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,200.00	600
27	1 TO REMOVE AND REFIT INNER TRIM	120.00	50
		2,770.00	2,770.00
		Total	S\$ 6,227.16
		Add GST @ 7%	435.90
		Total Amount Payable	<u>S\$ 6,663.06</u>

TOTAL: SINGAPORE DOLLAR SIX THOUSAND SIX HUNDRED SIXTY THREE AND CENTS SIX ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

3.1K

Adrian L
L/S 04/06/21.
050mgs.
Total: 3863.02
L/S 3.1K