



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 6459 Mobile: 9687 4031

Email: yeeautopte ltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S: AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16

Singapore 079120

Estimate No: ES2100054

Date: 07 Jun 2021

Policy No:

Veh Reg No: SMQ57T

Make/Model: HONDA ODYSSEY 2.4 EXV-S CVT SR

Chassis No: JHMRC1890KC205615

Engine No: K24W72462084

Reg. Date: 07/11/2019

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Third Party

Accident Date: 04/06/2021

TP Veh Reg No: SKQ9981P

Estimate Repair Cost to Vehicle No :SMQ57T

Description	U/Price	Quantity	List Price S\$	Amount S\$
Net Price				
1 FRONT TYRE - RH	380.00	1 PC	380.00	?
2 FRONT WHEEL RIM - RH	800.00	1 PC	800.00	✓
			1,180.00	1,180.00
Spare Parts				
3 FRONT DOOR - RH	1,135.90	1 PC	1,135.90	✓
4 FRONT DOOR CHANNEL - RH	92.40	1 PC	92.40	X
5 FRONT DOOR GLASS OUTER MOULDING - RH	147.70	1 PC	147.70	X
6 FRONT DOOR HINGE - RH (TOP)	188.60	1 PC	188.60	X
7 FRONT DOOR HINGE - RH (LOWER)	188.60	1 PC	188.60	?
8 FRONT DOOR LOCK - RH	272.80	1 PC	272.80	X
9 FRONT DOOR LOCKER PANEL STEP COVER - RH	198.50	1 PC	198.50	X
10 FRONT DOOR OUTER HANDLE - RH	385.00	1 PC	385.00	X
11 FRONT DOOR PILLAR - RH	628.60	1 PC	628.60	X
12 FRONT DOOR REGULATOR GEAR - RH	278.60	1 PC	278.60	X
13 FRONT DOOR REGULATOR GEAR MOTOR - RH	334.90	1 PC	334.90	X
14 FRONT DOOR STICKER - RH	56.50	1 PC	56.50	✓
15 FRONT DOOR TRIM BOARD - RH	698.00	1 PC	698.00	?
16 FRONT DOOR WEATHERSTRIP - RH	179.50	1 PC	179.50	?
17 FRONT DOOR OUTER HANDLE - RH	195.50	1 PC	195.50	X
18 FRONT DOOR PROTECTOR - RH	485.10	1 PC	485.10	✓
19 REAR SLIDING DOOR - RH	1,112.30	1 PC	1,112.30	X
20 FRONT BUMPER	1,227.70	1 PC	1,227.70	X
21 FRONT BUMPER FOG LAMP - RH	527.40	1 PCS	527.40	X
22 FRONT BUMPER FOG LAMP BRACKET - RH	99.40	1 PC	99.40	X
23 FRONT BUMPER CHROME - RH	168.20	1 PC	168.20	?
24 FRONT BUMPER SIDE RETAINER - RH	52.60	1 PC	52.60	X
25 FRONT FENDER - RH	780.40	1 PC	780.40	✓
26 FRONT FENDER INNER SHIELD CLIPS	60.00	1 SET	60.00	X
27 FRONT FENDER SPLASH SHIELD - RH	245.30	1 PC	245.30	X
28 FRONT HEADLAMP - RH	2,245.80	1 PC	2,245.80	X
29 FRONT LOWER ARM - RH	531.40	1 PC	531.40	?
30 FRONT SHOCK ABSORBER - RH	435.80	1 PC	435.80	?
31 FRONT DOOR PROTECTOR CHROME - RH	185.15	1 PC	185.15	✓
32 FRONT FENDER LOWER PROTECTOR - RH	280.15	1 PC	280.15	✓
33 FRONT DOOR LOWER INNER GARNISH - RH	485.15	1 PC	485.15	X
	680.00	1 PC	680.00	?



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 675722

Tel: 6457 5700 Fax: 6252 8450 Mobile: 9687 4031

Email: yeeautopteLtd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16
Singapore 079120

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 04/06/2021
TP Veh Reg No: SKQ9981P

Estimate No: ES2100054
Date: 07 Jun 2021
Policy No:
Veh Reg No: SMQ57T
Make/Model: HONDA ODYSSEY 2.4
EXV-S CVT SR
Chassis No: JHMRC1890KC205615
Engine No: K24W72462084
Reg. Date: 07/11/2019

Estimate Repair Cost to Vehicle No :SMQ57T

Description	U/Price	Quantity	List Price	Amount
35 DRIVE SHAFT	890.15	1 PC	890.15	890.15
36 STABILIZER LINK	285.15	1 PC	285.15	285.15
			15,758.25	15,758.25
Labour				
37 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	2,000.00	1 JOB	2,000.00	2,000.00
38 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	2,000.00	1 JOB	2,000.00	2,000.00
39 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	200.00	1 JOB	200.00	200.00
40 TO REMOVE/REFIT FRONT PILLAR GLASS.	120.00	1 JOB	120.00	120.00
41 TO TOW VEHICLE TO WORKSHOP.	150.00	1 JOB	150.00	150.00
42 TO CHECK WIRING FUNCTIONS.	100.00	1 JOB	100.00	100.00
43 WHEEL ALIGNMENT	120.00	1 T	120.00	120.00
44 TO REMOVE/REPLACE UNDERCARRIAGE LABOUR.	300.00	1 PC	300.00	300.00
			4,990.00	4,990.00

Total S\$ 21,928.25

Add GST @ 7% 1,534.98

Total Amount Payable S\$ 23,463.23

TOTAL: SINGAPORE DOLLAR TWENTY THREE THOUSAND FOUR HUNDRED SIXTY THREE AND CENTS TWENTY THREE ONLY

For Yee Auto Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

AUTHORISED SIGNATURE