

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

7-Jun-21

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6009 B

1 pc	Bootlid		\$	1,119.00	DP
1 pc	Bootlid CRDI		\$	27.00	NEC
1 pc	Bootlid emblem		\$	29.00	NEC
1 pc	Bootlid lower garnish		\$	290.00	X R
1 pc	Boot lid lock		\$	99.00	X SVC
1 pc	Bootlid inner trim		\$	190.00	? X SVC
2 pcs	Rear license plate lamp @ \$30.00		\$	60.00	X SVC
2 pcs	Rear n/s & o/s tail lamps @ \$421.00	\$421	\$	842.00	Y L / CRK 2 X SVC
2 pcs	Bootlid rear n/s & o/s reflector @ \$350.00	\$350	\$	700.00	? X LH / DEF RH X SVC
1 pc	End panel		\$	250.00	? X R
1 pc	End panel garnish		\$	74.00	? / CRK
1 pc	Rear bumper		\$	696.00	CRK
1 pc	Rear bumper lower cover		\$	206.00	DEF
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$29	\$	58.00	? X LH / DEF RH X SVC
1 pc	Rear bumper inner sponge		\$	114.00	? / DEF
1 pc	Rear bumper reinforcement		\$	607.00	? / DD
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	\$53	\$	106.00	? X LH / DEF RH X SVC
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00		\$	36.00	? / DEF
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00		\$	36.00	? X SVC
2 pcs	Rear bumper n/s & o/s reflector @ \$46.00		\$	92.00	X SVC
				3,761	
			\$	5,633.00	
			Less 10%	\$	563.30
				\$	5,069.70

### S/NETT

1 set	Rear bumper clips		\$	48.00	NEC
1 set	Reverse sensor		\$	280.00	MIS
1 set	Bootlid lower garnish clips		\$	38.00	? X SVC
1 set	Bootlid inner trim clips		\$	28.00	? X SVC
1 set	End panel garnish clips	\$20	\$	28.00	? / NEC
1 set	Bootlid stickers		\$	100.00	NEC
1 pc	Rear number plate with casing		\$	50.00	Nec
				25 (casing only)	
				\$473	

7-Jun-21

**ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6009 B**

Sundry	\$	50.00	xnn
Towing Fee	\$	50.00	NEC
To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00	30
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00	xnn
To labour charge for dismantle and renew the accident damaged parts. To heat, weld & cut end panel. Including knock-out, straighten, repair, reshape and adjust of the same, etc	\$	4,400.00	540
To putty and spray painting on rear bumper, end panel, bootlid, bootlid lower garnish	\$	800.00	640
To apply rustproofing on the repaired and replaced panels.	\$	120.00	50
	\$	8,361.70	

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.**

NA2 LKK

7/6/2021 1730

LIS

4 DAYS

CHECK ITEM PHOTO

AFTER REPAIR PHOTO

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Acknowledged by Repairer**

Signature:

Date:

PARTS \$3,761.00

LESS 10% \$3,384.90

SINETT \$473.00

LABOUR \$1,310.00

TOTAL \$5,167.90

LESS LIS 20% \$4,134.32

LIS TOTAL \$4,100.00 / 4 REPAIR DAYS.