

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

7-Jun-21

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6009 B

1 pc	Bootlid	\$	1,119.00	/DD
1 pc	Bootlid CRDI	\$	27.00	/NEC
1 pc	Bootlid emblem	\$	29.00	/NEC
1 pc	Bootlid lower garnish	\$	290.00	X R
1 pc	Boot lid lock	\$	99.00	X SVC
1 pc	Bootlid inner trim	\$	190.00	?
2 pcs	Rear license plate lamp @ \$30.00	\$	60.00	X SVC
2 pcs	Rear n/s & o/s tail lamps @ \$421.00	\$	842.00	Y L / CRK 2 X SVC
2 pcs	Bootlid rear n/s & o/s reflector @ \$350.00	\$	700.00	?
1 pc	End panel	\$	250.00	?
1 pc	End panel garnish	\$	74.00	?
1 pc	Rear bumper	\$	696.00	/CRK
1 pc	Rear bumper lower cover	\$	206.00	/DEF
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$	58.00	?
1 pc	Rear bumper inner sponge	\$	114.00	?
1 pc	Rear bumper reinforcement	\$	607.00	?
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	\$	108.00	?
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$	36.00	?
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$	36.00	?
2 pcs	Rear bumper n/s & o/s reflector @ \$46.00	\$	92.00	X SVC
		\$	5,633.00	
		\$	563.30	Less 10%
		\$	5,069.70	

### S/NETT

1 set	Rear bumper clips	\$	48.00	/NEC
1 set	Reverse sensor	\$	280.00	/MIS
1 set	Bootlid lower garnish clips	\$	38.00	?
1 set	Bootlid inner trim clips	\$	28.00	?
1 set	End panel garnish clips	\$	28.00	?
1 set	Bootlid stickers	\$	100.00	/NEC
1 pc	Rear number plate with casing	\$	50.00	
				25 (casing only)

7-Jun-21

**ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6009 B**

Sundry	\$ 50.00	x NN
Towing Fee	\$ 50.00	/ NFE
To dismantle / replace reverse sensor to new bumper and reset to the same	\$ <del>120.00</del>	30
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00	x NN
To labour charge for dismantle and renew the accident damaged parts. To heat, weld & cut end panel. Including knock-out, straighten, repair, reshape and adjust of the same, etc	\$ <del>4,400.00</del>	540
To putty and spray painting on rear bumper, end panel, bootlid, bootlid lower garnish	\$ <del>800.00</del>	640
To apply rustproofing on the repaired and replaced panels.	\$ <del>120.00</del>	50
	<u>\$ 8,361.70</u>	

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.**

NA2 LKK

7/6/2021 1730

LIS

4 DAYS

CHECK ITEM PHOTOS

AFTER REPAIR PHOTOS

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Acknowledged by Repairer**

Signature:

Date: