



GOLDBELL ENGINEERING

Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD
Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3876
Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500
Website: www.goldbell.com.sg
Co. Reg. No.: 198003963G

Not Authorised
Return B4 part

Page 1 / 3

ESTIMATE

Date	: 07/06/2021	Reg No	: SMJ6684E
To	: CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	Model	: HONDA JAZZ
Attn.	:	Chassis No	: JHMGK3850KS210787
Office / Mobile	:	Engine No	: L13B14100374
Email Address	:	Quotation No.	: 135129
		Ref. No.	:
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 03/06/2021
Attn.	: KONYINSIEW	Policy No.	:
Office / Mobile	: +65 6861 0007	Claim Type	: TP CLAIMS - CHINA TAIPING
Email / Fax No.	: KonYinSiew@goldbell.com.sg	Workshop	: ANG MO KIO

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price	
1		LH FRONT DOOR	1	510.00	0	510.00	510.00	✓
2		LH FRONT DOOR LOCK	1	180.00	0	180.00	180.00	?
3		LH FRONT DOOR CATCH	1	20.00	0	20.00	20.00	X
4		LH FRONT DOOR WINDOW REGULATOR	1	180.00	0	180.00	180.00	?
5		LH FRONT DOOR SPEAKER	1	55.00	0	55.00	55.00	?
6		LH FRONT DOOR WINDOW CHANNEL	1	50.00	0	50.00	50.00	?
7		LH FRONT DOOR WINDOW LOWER MOULDING	1	55.00	0	55.00	55.00	X
8		LH FRONT DOOR SEAL	1	30.00	0	30.00	30.00	✓
9		LH FRONT DOOR HINGE UPPER	1	45.00	0	45.00	45.00	X
10		LH FRONT DOOR HINGE LOWER	1	45.00	0	45.00	45.00	X
11		LH FRONT DOOR CHECKER	1	45.00	0	45.00	45.00	✓
12		LH REAR DOOR	1	510.00	0	510.00	510.00	✓
13		LH REAR DOOR LOCK	1	180.00	0	180.00	180.00	?
14		LH REAR DOOR CATCH	1	20.00	0	20.00	20.00	X
15		LH REAR DOOR WINDOW REGULATOR	1	180.00	0	180.00	180.00	?
16		LH REAR DOOR SPEAKER	1	55.00	0	55.00	55.00	X
17		LH REAR DOOR WINDOW LOWER MOULDING	1	55.00	0	55.00	55.00	X
18		LH REAR DOOR WINDOW CHANNEL	1	50.00	0	50.00	50.00	?
19		LH REAR DOOR SEAL	1	50.00	0	50.00	50.00	✓
20		LH REAR DOOR HINGE UPPER	1	45.00	0	45.00	45.00	X
21		LH REAR DOOR HINGE LOWER	1	45.00	0	45.00	45.00	✓
22		LH REAR DOOR CHECKER	1	45.00	0	45.00	45.00	?
23		LH REAR FENDER	1	600.00	0	600.00	600.00	X
24		REAR BUMPER	1	250.00	0	250.00	250.00	X
25		REAR BUMPER RETAINER LH	1	15.00	0	15.00	15.00	X
26		LH "B" PILLAR	1	590.00	0	590.00	590.00	X

PARTS TOTAL :

3,905.00



GOLDBELL
ENGINEERING

Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD
Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676
Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500
Website: www.goldbell.com.sg
Co. Reg. No.: 198003963G

Page 2 / 3

ESTIMATE

Date : 07/06/2021
To : CHINA TAIPING INSURANCE
(SINGAPORE) PTE. LTD.
Attn. :
Office / Mobile :
Email Address :

Reg No : SMJ6684E
Model : HONDA JAZZ
Chassis No : JHMGK3850KS210787
Engine No : L13B14100374
Quotation No. : 135129
Ref. No. :
D.O.A. : 03/06/2021
Policy No. :
Claim Type : TP CLAIMS - CHINA TAIPING
Workshop : ANG MO KIO

From : GOLDBELL ENGINEERING PTE LTD
Attn. : KONYINSIEW
Office / Mobile : +65 6861 0007
Email / Fax No. : KonYinSiew@goldbell.com.sg

SPECIAL NETT ITEMS

1	LH DOOR TRIM CLIPS (SET)	2	60.00	7
2	BODY SEALANT	1	na 120.00	X
3	REAR BUMPER CLIPS (SET)	1	na 30.00	X
4	RIM	1	na 800.00	✓

PARTS TOTAL: 1010.00

LABOUR CHARGES

1	TO REMOVE, REFIX & REPAIR AFFECTED DAMAGED PARTS. INCLUDING KNOCK OUT, WELD AND STRAIGHTEN ON THE AFFECTED PARTS	C600	2400.00	1800
2	TO TRANSFER DOOR COMPARTMENT / WINDOW GLASS / REGULATOR / LOCK / MECHANISM, ETC		700.00	360 360
3	TO CHECK AND RECONNECT ALL NECESSARY WIRING		150.00	20
4	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC	C350	1750.00	1400

LABOUR TOTAL : 5,000.00

SUB-TOTAL : 9,915.00

GST @ 7% for \$ 9,915.00 694.05

GRAND TOTAL (S\$) : 10,609.05

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FUSO

AIRMAN.

biSAFE

