

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

7-Jun-21

ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHB 8889 U

1 pc	Rear bumper	\$	459.40	/CRK
1 pc	Rear bumper reinforcement	\$	294.80	NO?
2 pcs	Rear bumper reinforcement n/s & o/s lower bracket @ \$10.00	\$	30.00	?
1 pc	Rear bumper reinforcement centre lower bracket	\$	15.00	?
1 pc	Antenna Assy- Smart Key	\$	41.90	?
1 pc	Lamp Assy- Rear fog	\$	201.50	/DEF
2 pcs	Rear bumper n/s & o/s stay @ \$138.10	\$	276.20	?
2 pcs	Rear bumper n/s & o/s side bracket @ \$33.10	\$	66.20	?
1 pc	Moulding Assy- Rear bumper center	\$	216.50	/DEF
1 pc	Rear licence lamp Assy	\$	47.50	/DEF
1 pc	Rear bumper lower lip	\$	60.40	XSVL
1 pc	Rear bumper lower cover	\$	216.50	Operated
1 pc	Rear bumper cap hook	\$	9.10	XSVL
1 pc	Rear bumper n/s & o/s reflector @ \$31.90	\$	63.80	/LX SVL
1 pc	Camera Assy- Back view	\$	899.90	XSVL / SCR
1 pc	o/s reflector	\$	353.70	/CRK
1 pc	o/s tail lamp	\$	362.60	/CRK
1 pc	End panel	\$	532.00	?
1 pc	End panel garnish	\$	584.00	?
1 pc	Tail gate emblem	\$	28.00	/NEK
1 pc	Tail gate lock	\$	224.00	/DEF
	Tail gate striker	\$	28.40	/XSVL
1 pc	Tail gate	\$	2,480.40	/DD
1 pc	Tail gate weatherstrip	\$	127.40	/DEF
1 pc	Glass Assy- Tailgate lower	\$	384.90	/CRK
		\$	8,004.10	
	Less 20%	\$	1,600.82	
		\$	6,403.28	

S/N

1 set	Rear bumper clips	\$	48.00	/NEK
1 set	Reverse sensor	\$	280.00	/DEF
1 pc	Rear number plate with casing	\$	50.00	/CRK

7-Jun-21

ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHB 8889 U

Sundry	\$ 50.00 ✓
To dismantle / replace reverse sensor to new bumper and reset to the same	\$ 120.00 30 30
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 50
To dismantle, vaccuum, clean up on the tail gate lower glass. To fit up tail gate lower glass to the same	\$ 120.00 30
To labour charge for dismantle and renew the accident damaged parts. To cut/weld and heating on the end panel. Including knock-out, straighten, repair, reshape and adjust of the same etc	\$ 1,200.00 540
To putty and spray painting on rear bumper, end panel, Rear bumper moulding center, rear bumper lower lip, tail gate	\$ 1,000.00 640
To apply rustproofing on the repaired and replaced panels.	\$ 200.00 30
	<hr/>
	\$ 9,651.28

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

NA2 LKK
7/6/2021 1720
PIP
4 days
CHECK ITEM PHOTO
BY PAINT PHOTO

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: