



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21006454/Auf3e2	
			Date: 25/06/2021	
			Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SMB 1447Z	Veh. Inspected	SJF 6162B
	Policy No.		Coverage (\$)	0.00
	Claim No.	BUS/06/21/5011	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	07/06/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	LEXUS RX400H HYBRID	c.c	3311
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	JTJHW31U602856327	Colour	BLACK
	Odometer	122902 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	235/55 R18	MICHELIN	6 mm
	L/H Front Tyre	235/55 R18	MICHELIN	6 mm
	R/H Rear Tyre	235/55 R18	MICHELIN	6 mm
	L/H Rear Tyre	235/55 R18	MICHELIN	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	02/06/2021	Inspection Date	08/06/2021
	Survey held at	YSK AUTO WORKSHOP 1 KAKI BUKIT AVE 6 AUTOBAY #01-71 SINGAPORE 417883		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	