

TP SMRT.  
Hi Zhen.

SJF6162B. 2008 June

Lexus RX400 Hybrid. 3311CC

JTJHW3LU602856327

Rear Bumper	del d	998.40 ✓
Rear Bumper Clips	nu	50(SN) ✓
Rear Bumper Side Molder	x02 nu	$64.4 \times 2 = 128.80$
Rear Bumper Top Moulding	del d	241.50 ✓
Rear Bumper Reflector	x02 nu	$142.4 \times 2 = 284.80$ ✓
Rear Bumper Sponge	amb d	185.20. ✓
Rear Bumper Reinforcement.	Dental	881.60 ✓
Rear Bumper Lower Garnish.	nu	329.40 +
Reverse Sensor	x 04 2 pieces	$250 \times 4 = 1000$ SW
<del>Reverse Sensor Wire Harness</del>		<del>=====</del>
Rear End Panel	Pys del d	261.50 +
Rear End Panel Top Garnish.	nu	314.10 ✓
Rear End Panel Top Garnish Clips		20(SN) ✓

SJF6162B.

Rees End Panel Sealant. <sup>AP</sup> m 60(su) x

Tailhup x 02 <sup>XL</sup> m 557.1 x 2 = 1114.20 x

Tailgate <sup>Dented</sup> 1785.20 /

Tailgate Lock <sup>Dryd</sup> 562.40 /

Tailgate Weatherstripe <sup>AP</sup> m 315.40 x

Tailgate Lower Trim Board <sup>AP</sup> 468.90 x

Tailgate Lower Trim Board clips. <sup>AP</sup> m 30(su) x

Tailgate Outer Moulding. <sup>could</sup> 295.40 /

Tailgate Outer Moulding clips. <sup>m</sup> 20 /

Tailgate Lamp x 02 <sup>could</sup> 420.4 x 2 = 840.80 ✓

Tailgate Glass Moulding. <sup>Ne</sup> 175.50 /

Tailgate Glass Sealant. <sup>m</sup> 60(su) /

Lexus Logo. 105.50 /

Lexus Word'ing. <sup>Ne</sup> 88.10 /

RX 400 Word'ing. 89.70 /

Borneo Motor Logo. 65 /

SJF6162B.

Panel Beating

~~1200~~ 600

Spray Painting

~~1000~~ 700

Wiring

~~50~~ 30

To remove reverse sensor

~~100~~ 50

To remove upholstery.

~~180~~ 40

To spray tuff coat.

~~180~~ 40

To transfer tailgate fittings.

~~150~~ 80

To remove tailgate glass.

~~180~~ 120

List: 7077.60 Labour: 1660

ten 10%: 6369.84 total: 8149.84

SN: 130

4/5: 6.51K ✓  
05 Days.

KK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total \$12,966.62