

T K MOTOR WORKSHOP

1 KAKI BUKIT AVE 6 #02-56

SINGAPORE 417883

TEL : 96273323 FAX 68442641

CO.REG NO: 53049097-L

XU SHAOHONG , BERNARD

BLK 554 , WOODLANDS DRIVE 53 , #03-21

SINGAPORE 730554

DATE :-15/06/2021

TP Ching.

Denise.

ACCIDENT DATE : 04/06/2021

MODEL : MERCEDES BENZ / C180K

CHASSIS NO : WDD2040462A092010

ESTIMATE COST OF REPAIR BILL TO MERCEDES BENZ CAR NO : SLK3644Y

1 PC REAR BOOTLID

Dented

S\$ 1455 ✓

1 PC REAR BOOTLID INNER TRIMBOARD HOLDER GARNISH

no
m

295 +

1 PC REAR BOOTLID LOCK

Dented

235 ✓

1 PC REAR BOOTLID RUBBER

cut

158 ✓

1 PC REAR BOOTLID CHROME HANDLE

no m

217 X

4 PC REAR BOOTLID EMBLEM

no

75x4=300 ✓

1 PC REAR NO. PLATE

no m

26.00 S/NETT X

1 PC REAR NO. PLATE COVER

could

26.00 S/NETT ✓

2 PC REAR TAILLAMP

could

542x2=1084. ✓

2 PC REAR TAILLAMP SIDE GARNISH

torn

35x2=70 ✓

10 PC REAR TAILLAMP SIDE GARNISH CLIPS

no

2x10=20 ✓

1 PC REAR END PANEL

Dented

926 ✓

1 PC REAR END PANEL GARNISH

could

198 ✓

6 PC REAR END PANEL GARNISH CLIPS

no

2x6=12 ✓

1 PC REAR SPAREWHEEL PANEL

no

825 X

1 PC REAR SPAREWHEEL PANEL TYRE HOLDER

could

\$ 315 ✓

T K MOTOR WORKSHOP

1 KAKI BUKIT AVE 6 #02-56

SINGAPORE 417883

TEL : 96273323 FAX 68442641

CO.REG NO: 53049097-L

ESTIMATE COST OF REPAIR BILL TO MERCEDES BENZ CAR NO : SLK3644Y

1 PC REAR SPAREWHEEL PANEL TYRE TOOLS COMPARTMENT GARNISH		\$	
1 PC REAR SPAREWHEEL COVER GARNISH	Defend	295	✓
1 PC REAR SPAREWHEEL FIBER BASE PANEL	could	415	✓
1 PC REAR SPAREWHEEL FIBER BASE PANEL SEALANT	new	60	✓
1 PC REAR SPARE TYRE	new	280	✓
1 PC REAR BUMPER	Defend	1345	✓
8 PC REAR BUMPER CLIPS	new	3x8=24	✓
1 SET 4 PC REAR REVERSE SENSOR WITH MONITOR SCREEN	Defend	\$480.00 S/NETT	300(SN) ✓
1 PC REAR REVERSE CAMERA	new	\$380.00 S/NETT	✓
1 PC REAR BUMPER CENTRE CHROME MOULDING	new	190	✓
2 PC REAR BUMPER SIDE CHROME MOULDING	new	120x2=240	✓
1 PC REAR BUMPER TOW COVER	Missing	48	✓
2 PC REAR BUMPER SIDE RETAINER	new	74x2=148	✓
1 PC REAR BUMPER REINFORCEMENT BEAM	Best	625	✓
1 PC REAR BUMPER CENTRE SUPPORT BRACKET GARNISH	could	195	✓
2 PC REAR BUMPER SIDE SUPPORT BRACKET GARNISH	new	45x2=90	✓
4 PC REAR BUMPER SIDE SUPPORT BRACKET GARNISH CLIPS	new	4x2=8	✓
1 PC REAR EXHAUST PIPE	Repair	1457	✓
1 PC REAR EXHAUST PIPE LEFT HAND HEAT SHIELD	new	105	✓
4 PC REAR EXHAUST PIPE LEFT HAND HEAT SHIELD CLIPS	new	\$ 284=8	✓

8210

S.N: 326.

Len 10% = 7389

T K MOTOR WORKSHOP
1 KAKI BUKIT AVE 6 #02-56
SINGAPORE 417883
TEL : 96273323 FAX 68442641
CO.REG NO: 53049097-L

ESTIMATE COST OF REPAIR BILL TO MERCEDES BENZ CAR NO : SLK3644Y

LABOUR CHARGE

TO CHECK WIRING	\$50.00	30
SPRAY PAINTING	\$1,400.00	900
TO REMOVE & REFIX REAR INTERIOR UPSHOLY	\$80.00	60
TO REMOVE & REFIX REAR EXHAUST PIPE	\$80.00	✓
TO REMOVE & REFIX REAR SPAREWHEEL FIBER BASE PANEL	\$80.00	✓
TO APPLY UNDERCOATING ON THE REPAIRED & REPLACED PANEL FOR RUST PROTECTION	\$80.00	✓
TO MEASURE , DRILL THE REPLACED REAR BUMPER , POSITION & REINSTALL REAR REVERSE SENSOR , CONTROL UNTIL , CAMERA ASSY & TEST FOR FUNCTIONING	\$80.00	✓
TO RESET FAULT CODE & CARRY OUT DIAGNOSIC CHECK	\$120.00	X
LABOUR CHARGE FOR PANEL BEATING & WELDING , REMOVING ALL DAMAGE PARTS AND REPLACING OF THE NEW PARTS ETC.	\$1,200.00	900

13585

2210

TOTAL S\$

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

total: 9925

H/s: T91C

08 Days