

REPAIR ESTIMATE*

VEHICLE NO SH7294E

02/06/21

MAKE :

MODEL HYU-140

Qty	Parts Description/ Labour	Type	CHIANG/NTUC Unit Price	Amount
1	REAR BUMPER COVER			\$1,106.00
2	REAR BUMPER BRACKET SIDE LH/RH		\$35.60	\$71.20
10	REAR BUMPER CLIPS		\$2.20	\$22.00
2	REAR BUMPER REFLECTOR LH/RH		\$32.00	\$64.00
1	REAR BUMPER UNDER COVER			\$228.00
	SUB TOTAL			\$1,491.20
	20.00%			\$298.24
	DISCOUNTED TOTAL			\$1,192.96
1	REVERSE SENSOR 10%			\$135.70
1	REAR BUMPER MAT			\$50.00
				\$172.13
	Labour Charge			
	Panel Beating		280	\$480.00
	Spray Painting Charge		250	\$300.00
	Remove/refix reverse sensor		30	\$60.00
	Tuff Kote		560	\$60.00
	Check Lighting		1816.93	\$60.00
	TOTAL LABOUR			\$960.00
	ESTIMATE TOTAL			\$2,325.09
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tanphn 97495749 Duration
 'WP' 3/6/21 @ 415, n
 2 days
 4/3 Repair after repair
 Tanphn e (Khan to over)