

Our Job Ref No : 305471849
Date : 05/06/21

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : TAUFIKH
Vehicle Reg No. : SH7294E

Fax :


01/06/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- Z The repair job shall bill to: NTUC SKX4544P
2. The finalized amount shall be:
- (a) Spare Parts after List discount _____
- (b) Labour Charges _____
- Total for Part-By-Part Repair Cost** _____
- (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: _____
Final Lumpsum Repair cost \$1,450.00

3. Estimated normal period for repairs: 2 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance.

We confirm the estimates and
finalized amount

Signature : 
Name : CHIANG
Tel : 62148314
Fax : 65468156

Signature : taufikh
Name : Taufikh
Date : 14/6/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

REPAIR ESTIMATE*

VEHICLE NO SH7294E

02/06/21

MAKE :

MODEL HYU- I40

Type

CHIANG/NTUC

Qty	Parts Description/ Labour		Unit Price	Amount
1	REAR BUMPER COVER			\$1,106.00
2	REAR BUMPER BRACKET SIDE LH/RH		\$35.60	\$71.20
10	REAR BUMPER CLIPS		\$2.20	\$22.00
2	REAR BUMPER REFLECTOR LH/RH		\$32.00	\$64.00
1	REAR BUMPER UNDER COVER			\$228.00
	SUB TOTAL	1356.00		\$1,491.20
	20.00%			\$298.24
	DISCOUNTED TOTAL	1084.80		\$1,192.96
1	REVERSE SENSOR 10%			\$135.70
1	REAR BUMPER MAT	172.13		\$50.00
				\$172.13
	Labour Charge			
	Panel Beating		280	\$480.00
	Spray Painting Charge		250	\$300.00
	Remove/refix reverse sensor		30	\$60.00
	Tuff Kote		X	\$60.00
	Check Lighting		X	\$60.00
	TOTAL LABOUR	560		\$960.00
	ESTIMATE TOTAL	1586.00		\$2,325.09
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

S/pb

Tanpha 97495749 Duration
 up 3/6/21 @ 415.00
 2 days
 4/5 Repair after repair
 Tanpha 97495749