

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Tan Kah Leong

Date: 17 Aug 2021

**Preliminary Advice**

Insured Vehicle No	: GBC7505A	Accident Date	: 26/05/2021
TP Vehicle No	: SKZ1337E	Assignment Date	: 07/06/2021
Make	: BMW M235I	Est. Duration of Repair	: 2
Date of Inspection	: 08/06/2021		
Inspection At	: YSK AUTO WORKSHOP (HQ) NO.1 KAKI BUKIT AVENUE 6, #01-49 AUTOBAY SINGAPORE 417883		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,904.00
Revised Amount	:S\$	4,492.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,492.00
 Lump Sum Repair	 :S\$	 3,600.00

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.