

Co. Reg. No.: 201416720C

1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883

Tel: 6636 9100 Fax: 6636 9113

Date: 04/06/2021

Ashes.

TO:

India International Insurance Pte Ltd

64 Cecil Street #04-02 IOB Building Singapore 049711 Our Customer: Uniconcept Pte Ltd

Vehicle No : GBD5283Y Model : Toyota Dyna

Manufacture Year: 2014
Date of Accident: 4/6/2021

Total Estimate Repair Days: 5 Total Pages: 1

Attn: Motor Claims Department

Fax: 6224 4174

Re: Repair Estimate For Third Party Claim against SLL1759H

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Tail gate stopper LH	1	\$121.60	\$121.60	+
2	Tail gate stopper bracket LH	1	\$183.20	\$183.20	+
3	Lower lever lock LH	1	\$264.20	\$264.20	<i>x</i> .
4	Rear fender LH	2	\$255.00	510 \$255.00	
5	Rear mudflap LH Nen	1	\$98.00	\$98.00	+
6	Side deck panel LH RX	1	repair	repair	×.
7	Side gate LH	1	\$1,550.00	\$1,550.00	<i>U</i>
8	Side gate hinges New	2	\$85.60	\$171.20	t
	2010		Total	\$2,643.20	
-	2000		Less 25%	\$660.80	
	1543	*	Sub-Total 1	\$1,982.40	
В.	Spare Parts (S/Nett)				
1	Company artwork	1	\$300.00	\$300.00	200.
	Real In lyon & 380 loy	W)	Sub-Total 2	\$300.00	
	Wt 150	To	tal for Parts	\$2,282.40	
C.	Labour	V			
1	To check wiring.			\$20.00	4.
2	Panel beating charges to remove and replace knock and reshape damaged parts & areas.		and weld, to	\$600.00	300
3	Spray painting all affected parts & areas.			\$600.00	- 30
4	To spray anti-rust undercoat.			\$30.00	120
			Total Labour	\$1,250.00	630
		Total	Repair Cost	\$3,532.40	

Yours faithfully,

LKK Auto Consultants hence notify the Repairer of the following:

To resurvey before/after spray painting
To display damaged part(s) during resurvey

Parts prices are subject to confirmation
Third party survey is on a "Without Prejudice" basis

No illegal prodification(s) is allowed
Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Date:

Surveyor's Details		
Name	Adrin Co	
Contact	96853735	
Survey Date	08/66/21	
Recommender	Authorize / Not Authorize	
Before Paint	Yes / No	

04 Pmpi tolal: 2525 4/5: 2K