

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305472440

Date 06/09/21

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr NAZ

Vehicle Reg No. SHD4801M

Date of Accident : 07/06/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: AIG SGT1198T
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$796.12
 - (b) Labour Charges \$630.00
 - Total for Part-By-Part Repair Cost** \$1,426.12
 - (c) Lumpsum Repair (if applicable)
 - Total for Lumpsum repair cost after Less: 20%
 - Final Lumpsum Repair cost** _____
3. Estimated normal period for repairs: 2 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature : _____

Name : JUMANI

Tel : 62148315

Fax : 65468156

Signature : _____

Name : NAZ LKK

Date : 15/6/2021

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 09.06.2021

Time: 12:02:28

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305472440
REGN NO : SHD4801M
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 25.10.2019
DATE/TIME IN : 07.06.2021 08:50
ACCIDENT DATE : 07.06.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52	✓CRK
0002 04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00	✓SCR
0003 04-01-0104-1150-A	PROTECTOR MAT	1 N	50.00	2.00-	50.00	✓NEC
0004 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	✓NEC

SUB-TOTAL : 796.12

JOB NATURE

0000 PB	PANEL BEATING (SHD4801M)	350.00	✓
0001 SP	SPRAYPAINT CHARGE	250.00	✓
0002 L	REMOVE/REFIX REVERSE SENSOR	30.00	✓

SUB-TOTAL : 630.00

TOTAL : 1,426.12

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

COMFORT TRANSPORTATION PTE LTD
REPAIR ESTIMATE

Vehicle No.: SHD4801M
Make : HYUNDAI
Model : IONIQ
DOA : 7/6/2021

Date : 7/6/2021
Insurance: AIG
MVA : JUMANI

Qty	Parts Description / Labour	Qty	Unit Price	Amount
1	REAR BUMPER ASSY	1		\$459.40
2	REAR BUMPER CLIPS	10		\$22.00
3	REAR BUMPER MOULDING CENTRE	1		\$451.25
4	REAR BUMPER BEAM	1		\$394.80
5	REAR FOG LAMP	1		\$201.50
6	ANTENNA-SMART KEY	1		\$40.50
SUB TOTAL				\$1,569.45
LESS 20%				\$313.89
DISCOUNTED TOTAL				\$1,255.56
1	REAR BUMPER MAT			\$50.00
				\$50.00
Labour Charge				
PANEL BEATING				\$400.00
SPRAYPAINT				\$300.00
REMOVE/REFIX REVERSE SENSOR				\$80.00
TOTAL LABOUR				\$780.00
ESTIMATE TOTAL				\$2,085.56

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be

NA2 LKK
8/6/2021 1645
PIL
2 DAYS
AFTER PAINT PHOTOS

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date: