

# HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

## ESTIMATE

MROS3REE104150644

DAWN ENTERPRISES  
21 SELETAR WEST FARMWAY 1  
S 798125

TP China.  
Justin.

Vehicle No :SKH 4897 E  
Make/Model :TOYOTA ALTIS  
Accident date :29.05.2021

| No                | DESCRIPTION  | Qty           | Amount (\$\$)                 |
|-------------------|--|---------------|-------------------------------|
| <u>List Items</u> |  |               |                               |
| 1                 | Rear windscreen rubber <i>new</i>                          | 1             | \$ 89.30 ✓                    |
| 2                 | Rear bootlid <i>Distorted</i>                              | 1             | \$ 754.70 ✓                   |
| 3                 | Rear bootlid hinges @ \$56.40 <i>new</i>                   | 2             | \$ 112.80 ✗                   |
| 4                 | Rear bootlid upper lock <i>Dented</i>                      | 1             | \$ 105.60 ✓                   |
| 5                 | Rear bootlid lower lock <i>new</i>                         | 1             | \$ 38.50 ✗                    |
| 6                 | Rear bootlid weather strip <i>ut</i>                       | 1             | \$ 205.20 ✓                   |
| 7                 | Rear bootlid handle <i>cracked</i>                         | 1             | \$ 350.50 ✓                   |
| 8                 | Rear bootlid centre emblem                                 | 1             | \$ 58.30 ✓                    |
| 9                 | Rear bootlid "1.6" emblem                                  | 1             | \$ 32.50 ✓                    |
| 10                | Rear bootlid "Dual" emblem                                 | 1             | \$ 46.60 ✓                    |
| 11                | Rear bootlid "VVTI" emblem                                 | 1             | \$ 46.60 ✓                    |
| 12                | Rear bootlid "Corolla" emblem                              | 1             | \$ 46.60 ✓                    |
| 13                | Rear bootlid "Altis" emblem                                | 1             | \$ 46.60 ✓                    |
| 14                | Rear bootlid reflector @ \$161.50 <i>LH cracked, RH ut</i> | 2             | \$ 323.00 ✓                   |
| 15                | Rear bootlid cable <i>had new</i>                          | 1             | \$ 58.10 ✗                    |
| 16                | Rear bootlid insulation <i>torn</i>                        | 1             | \$ 174.10 ✓                   |
| 17                | Rear lamp @ \$480.00 <i>cracked</i>                        | 2             | \$ <del>960.00</del> 594      |
| 18                | Rear lamp housing @ \$84.10 <i>RH Dented</i>               | 2             | \$ <del>168.20</del> ✗ 84.10  |
| 19                | Rear lamp lower garnish @ \$88.90 <i>new</i>               | 2             | \$ 177.80 ✗                   |
| 20                | Rear end panel <i>dented</i>                               | 1             | \$ 668.90 ✓                   |
| 21                | Rear end panel top garnish <i>dented</i>                   | 1             | \$ 202.70 ✓                   |
| 22                | Rear bumper <i>Distorted</i>                               | 1             | \$ 486.50 ✓                   |
| 23                | Rear bumper side retainer @ \$70.40 <i>new</i>             | 2             | \$ 140.80 ✓                   |
| 24                | Rear bumper bracket @ \$87.10 <i>Dented</i>                | 2             | \$ 174.20 ✓                   |
| 25                | Rear bumper lower reflector @ \$37.20 <i>new</i>           | 2             | \$ 74.40 ✗                    |
| 26                | Rear bumper sponge <i>cracked</i>                          | 1             | \$ 123.50 ✓                   |
| 27                | Rear fender @ \$927.20 <i>RH Buckled</i>                   | 2             | \$ <del>1,854.40</del> 927.20 |
| 28                | Rear fender inner trim @ \$351.70 <i>RH torn</i>           | 2             | \$ <del>703.40</del> ✗ 351.70 |
| 29                | Rear spare tyre top board <i>dented</i>                    | 1             | \$ 276.60 ✓                   |
| 30                | Rear number plate lamp @ \$58.20 <i>new</i>                | 2             | \$ 116.40 ✗                   |
| 31                | Rear spare tyre well <i>Reps</i>                           | 1             | \$ 780.90 ✗                   |
|                   |  |               | \$ 9,397.70                   |
|                   |  | Less 25% Disc | \$ 2,349.43                   |
|                   |  | <b>Total</b>  | <b>\$ 7,048.28</b>            |

630980  
473235

# HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

## ESTIMATE

DAWN ENTERPRISES  
21 SELETAR WEST FARMWAY 1  
S 798125

Vehicle No :SKH 4897 E  
Make/Model :TOYOTA ALTIS  
Accident date :29.05.2021

| No | DESCRIPTION | Qty | Amount (\$\$) |
|----|-------------|-----|---------------|
|----|-------------|-----|---------------|

### Special Nett Items

|   |  |       |                      |
|---|--|-------|----------------------|
| 1 | Rear number plate <i>Dated</i>                         | 1     | \$ 50.00 <i>30</i>   |
| 2 | Rear number plate holder <i>Debond</i>                 | 1     | \$ 50.00 <i>30</i>   |
| 3 | Rear bootlid insulation clips (1 set) <i>new</i>       | 1     | \$ 60.00 <i>30</i>   |
| 4 | Rear bumper clips (1 set) <i>new</i>                   | 1     | \$ 60.00 <i>30</i>   |
| 5 | Rear bumper reverse sensor @ \$380.00 <i>Dated 320</i> | 2     | \$ 760.00 <i>200</i> |
| 6 | Rear bootlid lock sensor <i>XH new</i>                 | 1     | \$ 106.80 <i>X</i>   |
|   |  | Total | \$ 1,086.80          |

### Labour Cost

|   |   |                         |             |
|---|---|-------------------------|-------------|
| 1 | To supply rear windscreen sealant                   | \$ 50.00 <i>✓</i>       |             |
| 2 | To supply rear end panel sealant                    | \$ 200.00 <i>60</i>     |             |
| 3 | Remove & reinstall rear windscreen                  | \$ 150.00 <i>120</i>    |             |
| 4 | Remove & reinstall roof lining + cushion            | \$ 200.00 <i>80</i>     |             |
| 5 | Remove & reinstall reverse sensor                   | \$ 150.00 <i>50</i>     |             |
| 6 | Remove & reinstall petrol tank                      | \$ 150.00 <i>X</i>      |             |
| 7 | Remove, replace & repair consistent to the accident | \$ 2,000.00 <i>1300</i> |             |
| 8 | Respray painting                                    | \$ 1,800.00 <i>1200</i> |             |
| 9 | Tuff kote   | \$ 100.00 <i>80</i>     |             |
|   |   | Total                   | \$ 4,800.00 |

Grand Total \$ 12,935.08

total: 7992.35

h/s: GAK

09 Days.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*Signature*  
*GAK* ✓