

Section A - Accident Details

Registration Number	SHF277S
Case Reference Number	TAX/06/21/2009
Registration Date	14/12/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	HAIDINOOR BIN MOHAMED
Type of Accident	Side Swipe
Accident Date and Time	4/6/2021 5:35 PM
Accident Reported Date and Time	5/6/2021 9:43 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24111173
Special Instruction to ARC, if any	TP/LEFT FRONT AND RIGHT PORTION / TOWED /AIG - LKK
Prepared Date and Time	5/6/2021 11:36 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,352.00	\$400.00
Total Spray Cost	\$4,446.00	\$880.00
Total Spare Part Cost	\$27,633.90	\$5,117.17
Total Other Cost	\$1,216.00	\$190.00
TOTAL COST	\$34,647.90	\$6,587.17
Lump Sum Total	\$34,650.00	\$6,600.00 (L/S)
Number of Repair Days	13.0	7.0
Prepared / Adjusted By	Ang Bang Kien	RASUL (LKK) / AIG
ARC / Surveyor Sign Off Date	10/06/2021 3:43 PM	10/06/2021 8:52 AM
Signature		
Remarks	Total number of repair days = 7 days. SUP = 0 day.	LUMP SUM / AFTER PAINT

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2106-0385	Invoice Number	
Quotation Date	23.06.2021	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$845.00	\$400.00
TO REPAIR LH PORTION	\$507.00	\$0.00
Total Labour	\$1,352.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00
TO RESPRAY FILLER RR BUMPER LH	\$180.00	\$0.00
TO REPSRAY FRONT HOOD	\$378.00	\$0.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
TO RESPRAY APRON PANEL RH	\$180.00	\$0.00
TO RESPRAY RIM	\$720.00	\$50.00
TO RESPRAY ROCKER PANEL MOULDING	\$360.00	\$0.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$0.00
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00
TO RESPRAY REAR DOOR RH	\$378.00	\$200.00
TO RESPRAY REAR FENDER RH	\$378.00	\$0.00
RESPRAY MIRROR COVER RH	\$180.00	\$30.00
Total Spray Painting & Panel Beating	\$4,446.00	\$880.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$480.00	\$30.00
TO CHECK & RESET SYSTEM FUNCTION	\$80.00	\$60.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TOWING CHARGE	\$56.00	\$40.00
Total Other Costs	\$1,216.00	\$190.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		5302847010	SUPPORT SUB-ASSY LOWER	0.00	\$397.40	0.00	\$0.00	Repair	Check	X R
		5211547050	SUPPORT, FR BUMPER RH	1.00	\$76.90	25.00	\$57.68	Replace	Replace	√ NEC
		5211647050	SUPPORT, FR BUMPER LH	0.00	\$82.30	0.00	\$0.00	Replace	Not Given	X NN
		5202147110	REINFORCEMENT FRONT UPPER	0.00	\$691.10	0.00	\$0.00	Replace	Check	X SVC
		5261147140	ABSORBER, FR BUMPER	0.00	\$70.30	0.00	\$0.00	Replace	Check	X SVC
		5210347010	EXTENSION SUB-ASSY, LH	0.00	\$116.30	0.00	\$0.00	Replace	Check	X SVC
		5210247020	EXTENSION SUB-ASSY, RH	0.00	\$116.30	0.00	\$0.00	Replace	Check	X SVC
		5213247010	REINFORCEMENT FRONT LOWER	0.00	\$238.50	0.00	\$0.00	Replace	Check	X SVC
		5261847090	ABSORBER, FR BUMPER LOWER	0.00	\$117.00	0.00	\$0.00	Replace	Check	X SVC
		5311247240	GRILLE, RADIATOR	0.00	\$165.00	0.00	\$0.00	Replace	Not Given	X NN
		5310147080	GRILLE SUB-ASSY	0.00	\$335.60	0.00	\$0.00	Replace	Not Given	X NN
		5216116010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace	√ NEC
		5142047030	COVER ASSY, ENGINE	0.00	\$180.10	0.00	\$0.00	Replace	Not Given	X NN
		5141047020	COVER ASSY, ENGINE UNDER CENTER SET	0.00	\$452.80	0.00	\$0.00	Replace	Not Given	X NN
		5144347020	COVER, ENGINE UNDER SIDE RH	0.00	\$76.90	0.00	\$0.00	Replace	Check	X SVC
		8121047020	LAMP ASSY, FOG, RH	1.00	\$910.20	10.00	\$819.18	Replace	Replace	√ SCR
		8114547691	UNIT, HEADLAMP, RH	1.00	\$2,558.90	10.00	\$2,303.01	Replace	Replace	√ SCR
		8101647690	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	0.00	\$486.40	0.00	\$0.00	Replace	Check	X SVC
		5330147110	HOOD SUB-ASSY	1.00	\$938.40	100.00	\$0.00	Replace	Old Damage	X NN
		5341047130	HINGE ASSY, HOOD, RH	0.00	\$57.00	0.00	\$0.00	Replace	Not Given	X NN
		5342047130	HINGE ASSY, HOOD, LH	0.00	\$57.00	0.00	\$0.00	Replace	Not Given	X NN
		8531947170	WIPER WASHER INLET	0.00	\$55.40	0.00	\$0.00	Replace	Check	X NN
		8531547160	WIPER WASHER JAR	0.00	\$183.60	0.00	\$0.00	Replace	Check	X NN
		8871047160	TUBE & ACCESSORY	0.00	\$574.40	0.00	\$0.00	Replace	Not Given	X NN
		5380147080	FENDER SUB-ASSY, FR, RH	1.00	\$933.10	25.00	\$699.83	Replace	Replace	√ BT
		7537447140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$52.90	25.00	\$39.68	Replace	Replace	√ NEC
		5387547070	LINER, FR FENDER, RH	1.00	\$198.40	25.00	\$148.80	Replace	Replace	√ DE
		5385147061	PAD, FR WHEEL RH	0.00	\$57.70	0.00	\$0.00	Replace	Not Given	X NN
		5380747020	SEAL SUB-ASSY, RH	0.00	\$50.20	0.00	\$0.00	Replace	Not Given	X NN
		5382747050	PROTECTOR, FR FENDER RH	0.00	\$90.40	0.00	\$0.00	Replace	Not Given	X NN
		5370147111	APRON SUB-ASSY, FRONT FENDER, RH	0.00	\$944.20	0.00	\$0.00	Replace	Not Given	X NN
		42611-47450	WHEEL, DISC FRONT	1.00	\$1,555.10	100.00	\$0.00	Replace	Repair	R
		4355047020	HUB & BEARING ASSY, RH & LH	0.00	\$554.20	0.00	\$0.00	Replace	Not Given	X NN
		5211947962	COVER, FR BUMPER	1.00	\$495.50	25.00	\$371.63	Replace	Replace	√ DE
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X NN
		4341047040	SHAFT ASSY, FRONT DRIVE, RH	0.00	\$1,295.70	0.00	\$0.00	Replace	Not Given	X NN
		4321147040	KNUCKLE, STEERING, RH	0.00	\$555.20	0.00	\$0.00	Replace	Not Given	X NN
		4510047240C0	WHEEL ASSY, STEERING	0.00	\$2,880.20	0.00	\$0.00	Replace	Not Given	X NN
		4504649255	END SET, TIE ROD, RH	0.00	\$155.90	0.00	\$0.00	Replace	Not Given	X NN
		4806847060	LOWER ARM SUB-ASSY, FRONT RH	0.00	\$631.60	0.00	\$0.00	Replace	Not Given	X NN

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 23/06/2021

User ID : PohSuan

	43330191 15	JOINT ASSY, LWR BALL , RH & LH	0.00	\$200.10	0.00	\$0.00	Replace	Not Given	X NN
	48510808 15	ABSORBER SET, SHOCK, FRONT RH	0.00	\$398.10	0.00	\$0.00	Replace	Not Given	X NN
	48811470 80	BAR, STABILIZER, FR	0.00	\$356.00	0.00	\$0.00	Replace	Not Given	X NN
	45510471 40	GEAR ASSY, STEERING	0.00	\$1,620.70	0.00	\$0.00	Replace	Not Given	X NN
	48820470 40	LINK ASSY, FRONT STABILIZER , RH & LH	0.00	\$196.70	0.00	\$0.00	Replace	Not Given	X NN
	75850479 10	MOULDING ASSY, BODY ROCKER PANEL , RH	0.00	\$576.00	0.00	\$0.00	Replace	Not Given	X NN
	87910474 50	MIRROR ASSY, OUTER REAR VIEW , RH	0.00	\$1,373.50	0.00	\$0.00	Replace	Not Given	X NN
	87915470 70A1	COVER, OUTER MIRROR, RH	1.00	\$89.50	100.00	\$0.00	Replace	Repair	R
	67001471 52	PANEL SUB-ASSY, FRONT DOOR RH	1.00	\$1,249.60	100.00	\$0.00	Replace	Repair	R
		STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	√ NEC
	68610470 40	CHECK ASSY, FRONT DOOR	0.00	\$153.50	0.00	\$0.00	Replace	Not Given	X NN
	68710121 51	HINGE ASSY, FRONT DOOR , UPPER RH	0.00	\$82.10	0.00	\$0.00	Replace	Not Given	X NN
	68730121 20	HINGE ASSY, FRONT DOOR , LOWER RH	0.00	\$92.10	0.00	\$0.00	Replace	Not Given	X NN
	67003472 10	PANEL SUB-ASSY, REAR DOOR , RH	1.00	\$1,243.90	100.00	\$0.00	Replace	Repair	X R
	68750201 22	HINGE ASSY, REAR DOOR , UPPER RH	0.00	\$83.30	0.00	\$0.00	Replace	Not Given	X NN
	68770520 31	HINGE ASSY, REAR DOOR , LOWER RH	0.00	\$73.30	0.00	\$0.00	Replace	Not Given	X NN
	68630470 50	CHECK ASSY, REAR DOOR	0.00	\$153.50	0.00	\$0.00	Replace	Not Given	X NN
	61601471 50	PANEL SUB-ASSY, FENDER REAR RH	0.00	\$824.80	0.00	\$0.00	Replace	Not Given	X NN
	65565470 10	PATCH, SIDE PANEL REAR END , RH & LH	0.00	\$33.70	0.00	\$0.00	Replace	Not Given	X NN
	65637470 60	LINER, REAR FENDER , RH	0.00	\$135.80	0.00	\$0.00	Replace	Not Given	X NN
	42611474 50	WHEEL, DISC	0.00	\$1,555.10	0.00	\$0.00	Replace	Not Given	X NN
	43550470 20	HUB & BEARING ASSY, RH & LH	0.00	\$554.20	0.00	\$0.00	Replace	Not Given	X NN
		PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace	√ NEC
	53802471 00	FENDER SUB-ASSY, FR , LH	0.00	\$933.10	0.00	\$0.00	Replace	Not Given	X NN
	75374471 40	EMBLEM, SIDE PANEL (HYBRID)	0.00	\$52.90	0.00	\$0.00	Replace	Not Given	X NN
	53876471 10	LINER, FR FENDER, LH	0.00	\$194.30	0.00	\$0.00	Replace	Not Given	X NN
	53852470 41	PAD, FR WHEEL LH	0.00	\$57.70	0.00	\$0.00	Replace	Not Given	X NN
	42611- 47450	WHEEL, DISC FRONT	1.00	\$1,555.10	25.00	\$1,166.33	Replace	Replace	√ SCR
		TYRE	1.00	\$126.74	0.00	\$126.74	Replace	Replace	√ PUN
	43550470 20	HUB & BEARING ASSY, RH & LH	0.00	\$554.20	0.00	\$0.00	Replace	Check	X SVC
	43420470 40	SHAFT ASSY, FRONT DRIVE , LH	0.00	\$1,175.10	0.00	\$0.00	Replace	Not Given	X NN
	43212470 40	KNUCKLE, STEERING, LH	0.00	\$555.20	0.00	\$0.00	Replace	Check	X NN
	45047491 95	END SET, TIE ROD, LH	0.00	\$155.90	0.00	\$0.00	Replace	Check	X NN
	48520804 92	ABSORBER SET, SHOCK, FRONT LH	0.00	\$398.10	0.00	\$0.00	Replace	Check	X NN
	48069470 60	LOWER ARM SUB-ASSY, FRONT LH	0.00	\$631.60	0.00	\$0.00	Replace	Check	X NN
	43330191 15	JOINT ASSY, LWR BALL , RH & LH	0.00	\$200.10	0.00	\$0.00	Replace	Check	X NN
	48811470 80	BAR, STABILIZER, FR	0.00	\$356.00	0.00	\$0.00	Replace	Check	X NN
	48820470 40	LINK ASSY, FRONT STABILIZER , RH & LH	0.00	\$196.70	0.00	\$0.00	Replace	Check	X NN
	51201470 71	FRONT CROSSMEMBER	0.00	\$2,502.10	0.00	\$0.00	Replace	Not Given	X NN
	65637470 60	LINER, REAR FENDER , RH	0.00	\$135.80	0.00	\$0.00	Replace	Not Given	X NN
	75860479 00	MOULDING ASSY, BODY ROCKER PANEL , LH	0.00	\$576.00	0.00	\$0.00	Replace	Not Given	X NN
	42611474 50	WHEEL, DISC	0.00	\$1,555.10	0.00	\$0.00	Replace	Not Given	X NN

		43550470 20	HUB & BEARING ASSY, RH & LH	0.00	\$554.20	0.00	\$0.00	Replace	Not Given
		58166470 30	COVER, FRONT FLOOR UNDER, LH	0.00	\$425.50	0.00	\$0.00	Replace	Not Given
		57628470 20	COVER ASSY, CENTER FLOOR UNDER, LH	0.00	\$390.20	0.00	\$0.00	Replace	Not Given
		52566479 00	FILLER, RR BUMPER, LH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given
		58399470 30	COVER, REAR FLOOR UNDER, LH	0.00	\$234.30	0.00	\$0.00	Replace	Not Given
		66259470 10	COVER, REAR FLOOR UNDER CENTER	0.00	\$222.60	0.00	\$0.00	Replace	Not Given
Total					\$44,540.28		\$5,864.13		

X SVC
X NN
X NN
X NN
X NN
X NN

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		51410470 20	COVER ASSY, ENGINE UNDER CENTER SET	1.00	\$452.80	25.00	\$339.60	Replace	Replace
		51420470 30	COVER ASSY, ENGINE	1.00	\$180.10	25.00	\$135.08	Replace	Replace
		51444470 10	COVER, ENGINE UNDER SIDE LH	1.00	\$76.90	25.00	\$57.68	Replace	Replace
Total					709.80		532.36		

√ SCR
√ SCR
√ SCR

6,396.49
 -20%
 5117.19 L/S \$6,600/-
 + 400.00
 + 1070.00
 6,587.19

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No large modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: