



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMK 1146U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	TORN	934.00	745.20
1	FRONT BUMPER BRACKET RIGHT	DEFORMED	60.00	60.00
1	FRONT BUMPER GRILLE WITH CHROME	NOT NECESSARY	496.00	-
1	SET FRONT BUMPER SENSOR	NOT WORKING	400.00	200.00
1	FRONT BUMPER TOWING COVER	NOT NECESSARY	38.00	-
1	FRONT BUMPER LOWER GARNISH	NOT NECESSARY	99.00	-
1	FRONT FOG LAMP RIGHT WITH GARNISH	NOT NECESSARY	318.00	-
1	FRONT HEADLAMP RIGHT	CUT	1,830.00	1,523.00
1	FRONT BONNET	BENT	1,660.00	970.50
1	FRONT BONNET LOCK	NOT NECESSARY	159.00	-
1	KIA EMBLEMS	NECESSARY	55.00	55.00
1	FRONT RIGHT FENDER	TO REPAIR SEE LABOUR	642.00	-
1	FRONT REINFORCEMENT	NOT NECESSARY	448.00	-
1	FRONT TOP PANEL SAMPLE	NOT NECESSARY	655.00	-
	LESS 20% DISCOUNT		-1,558.80	-710.74
			6,235.20	2,842.96
<u>LABOUR</u>				
	TO FIX & DISMANTLE AND REMOVE DAMAGED FRONTAL PORTIONS;AFFECTED DAMAGED PORTION.INCLUSIVE OF THE REPAIR OF FRONT RIGHT FENDER.		1,000.00	600.00
	TO APPLY ANTI RUST COAT AND AFFECTED AREAS. (NPA)	NOT NECESSARY	-	-
	TO CHECK WIRING.		120.00	30.00
	WELDING AND CUTTING OF AFFECTED PANELS,INCLUDING CHASSIS ALIGNMENT.	NOT NECESSARY	600.00	-
	SPRAY PAINTING FOR FRONTAL PORTIONS AFFECTED PARTS.		1,000.00	700.00
	REFOCUSING OF THE FRONT HEADLAMP.		180.00	30.00
	DIAGNOSE ECU SYSTEM AND RESET ERROR CODE.		120.00	120.00

Report Ref No. CS3/CTI21001592/T1qf3n2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	3D WHEEL ALIGNMENT. (NPA)	NOT NECESSARY	-	-
			3,020.00	1,480.00
GRAND TOTAL			9,255.20	4,322.96
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,450.00

Report Ref No. CS3/CTI21001592/T1qf3n2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.