



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.
78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

PAGE: 1

ATTN : MOTOR CLAIM DEPT
TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :
CLAIM TYPE : OWN DAMAGE
ACCIDENT DATE : 21/05/2021

ESTIMATE

NO : QUOT202106-000004(00)
DATE : 08/06/2021
POLICY NO : 999995580
VEH REG NO : SMW7987G
MAKE/MODEL : MERCEDES BENZ GLC300
4MATIC AMG LINE (R19 LED)
CHASSIS NO : W1N2539842F854934
ENGINE NO : 26492080086773
REG. DATE : 2020

Estimate Repair Cost to Vehicle No : SMW7987G

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Bonnet	1	1,400.00	1,400.00
2 Headlamp assy - LH	1	2,100.00	2,100.00
3 Front bumper	1	1,200.00	1,200.00
4 Front bumper reinforcement	1	310.00	310.00
5 Front bumper bracket - LH	1	48.00	48.00
6 Front bumper fog lamp cover - LH	1	78.00	78.00
7 Front bumper sensor seals	6	8.00	48.00
8 Front bumper clips	15	5.50	82.50
			5,266.50
		Add 10%	526.65
			5,793.15
LABOUR			
9 To panel beat and straighten front chassis frame, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00
10 To remove and refit front bumper sensor	1	100.00	100.00
11 To check and rectify wiring system	1	80.00	80.00
12 To putty and spray on affected areas	1	1,000.00	1,000.00
13 To reset and reprogramme headlamp fault code	1	350.00	350.00
			2,530.00

TOTAL S\$ 8,323.15

ADD GST @ 7% 582.62

GRAND TOTAL S\$ 8,905.77

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

SINGAPORE DOLLAR EIGHT THOUSAND NINE HUNDRED FIVE AND CENTS SEVENTY-SEVEN ONLY

Report
Lump Sum / I.B.I. ()