



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16

AIG BUILDING

SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 21/05/2021

ESTIMATE

NO : QUOT202106-000004(00)

DATE : 17/06/2021

POLICY NO : 999995580

VEH REG NO : SMW7987G

MAKE/MODEL : MERCEDES BENZ GLC300
4MATIC AMG LINE (R19 LED)

CHASSIS NO : W1N2539842F854934

ENGINE NO : 26492080086773

REG. DATE : 2020

Estimate Repair Cost to Vehicle No : SMW7987G

Description	Quantity	Unit Price	Amount
		S\$	S\$
SUPPLEMENTARY PARTS			
1 Bonnet buffer stopper - LH	1	25.00 CM	25.00 ✓
2 Headlamp bracket - LH	1	58.00 CM	58.00 ✓
3 Air duct - LH	1	40.00 CM	40.00 ✓
			123.00
		Add 10%	12.30
			135.30
		TOTAL	S\$ 135.30
		ADD GST @ 7%	9.47
		GRAND TOTAL	S\$ 144.77

SINGAPORE DOLLAR ONE HUNDRED FORTY-FOUR AND CENTS SEVENTY-SEVEN ONLY

FOR TONG LUCK AUTO PTE LTD