

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

08/06/2021 13:10

OWNER'S PARTICULARS

JOB-NO: 50113430

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHD8618A

TRANS: AUTO

CHASSIS: KMHC851CVKU121929

MAKE / MODEL: HYUNDAI / AE IONIQ HEV 1.6 Di

ENGINE: G4LEJU132413

OWNER'S INSURER: AXA INSURANCE SINGAPORE PTE LTD

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AREA	1.00	800.00	0.00	800.00		Y	300
2 TO RUST PROOFING OF THE AFFECTED AREA	1.00	170.00	0.00	170.00		Y	X
3 TO REMOVE AND REFIT NECESSARY ITEMS TO FACILITATE REPAIR	1.00	300.00	0.00	300.00		Y	X
4 TO DIAGNOSTIC, CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE	1.00	220.00	0.00	220.00		Y	X
5 TO READJUST AND REALIGN HEADLAMP AIM	1.00	150.00	0.00	150.00		Y	30
6 TO RESPRAY FRONT BUMPER	1.00	250.00	0.00	250.00		Y	200
7 TO RESPRAY FRONT FENDER PANEL	1.00	250.00	0.00	250.00		Y	200
8 TO RESPRAY FRONT BUMPER CENTER MOULDING	1.00	250.00	0.00	250.00		Y	100
9 TO RESPRAY FRONT BUMPER MOULDING	1.00	250.00	0.00	250.00		Y	100
TOTAL:		2,640.00	0.00	2,640.00			

MATERIALS

1 FRONT BUMPER COVER <i>SCR</i>	1.00	659.60	131.92	527.68	L	Y	
2 FRONT RH BUMPER RETAINER <i>X</i>	1.00	98.63	19.73	78.90	L	Y	
3 FRONT RH BUMPER SIDE SUPPORT BRACKET <i>X</i>	1.00	135.81	27.16	108.65	L	Y	
4 FRONT BUMPER CENTER UPPER MOULDING <i>SCR</i>	1.00	319.54	63.91	255.63	L	Y	
5 FRONT BUMPER ENERGY ABSORBER <i>X</i>	1.00	139.87	27.97	111.90	L	Y	
6 FRONT RH AIR CURTAIN DUCT ASSY <i>X</i>	1.00	156.99	31.40	125.59	L	Y	
7 FRONT RH BUMPER MOULDING <i>X</i>	1.00	194.58	38.92	155.66	L	Y	
8 FRONT RH DAY TIME RUNNING LIGHT ASSY <i>X</i>	1.00	599.66	119.93	479.73	L	Y	
9 FRONT RH FENDER LINER <i>X</i>	1.00	252.85	50.57	202.28	L	Y	
10 FRONT RH HEADLAMP <i>SCR</i>	1.00	2,110.50	422.10	1,688.40	L	Y	
11 FRONT RH FENDER PANEL <i>repair</i>	1.00	789.60	157.92	631.68	L	Y	
12 FRONT RH FENDER EMBLEM <i>na</i>	1.00	75.25	15.05	60.20	L	Y	
13 FRONT BUMPER CLIP SET <i>na</i>	1.00	85.00	0.00	85.00	S	Y	30
14 FRONT FENDER LINER CLIP SET <i>na</i>	1.00	75.00	0.00	75.00	S	Y	30
15 FRONT BUMPER RIVET SET <i>X</i>	1.00	70.00	0.00	70.00	S	Y	30
16 FRONT BUMPER CENTER UPPER MOULDING CLIP SET <i>na</i>	1.00	65.00	0.00	65.00	S	Y	30
17 FRONT FENDER "COMFORT DELGRO" STICKER <i>na</i>	1.00	250.00	0.00	250.00	S	Y	100/50
TOTAL:		6,077.88	106.58	4,971.30			

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
TOTAL PARTS & LABOUR :		8,717.88	1,106.58	7,611.30			

EXCESS/LOADING:\$ 0.00

No. Of Day: 3 days

RE-SURVEY BEFORE AFTER PAINTING

PART-BY-PART OR LUMP SUM: \$

DATE OF SURVEY: 08 / 06 / 21 @

SURVEYED BY: RASUL

CONTACT NO: 90010068 FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

Lump Sum

Labour = \$ 930

S/M = \$ 240

Parts = \$ 2531.91

L+s+p = \$ 3701.91 - 20% L/s
= \$ 2961.53

Final Amount = \$ 2961.53